

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 31. NR. 1 W. . .

Otsego COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 5-6-7-8

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

6" Cedar	-	N52E	-	24½ links
6" Cedar	-	S80W	-	19 links
12" Cedar	-	S60E	-	3½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was previously restored from government BTs by G. F. DeLaMater in 1935. Corner was monumented and witnessed by Forestry Division Land Surveyor to perpetuate a good corner and to identify state land boundaries. The NE government BT is down but has good face and marks.

Corner was placed and witnessed June 4, 1959.

SURVEYORS SEAL

SIGNED Kenneth J. Ostling DATE 6/5/59  
REGISTERED LAND SURVEYOR