## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

			OTSEGO	COUNTY
			T <u>31</u>	R <u>1</u> W
DESCRIPTION OF CORNER _	N 1/16 corner or	n N-S 1/4	line, Sec. 4,	T31NR1W
CORNER MONUMENT	Set 1½"x2' pipe 8	post		·
DATE MONUMENT PLACED AND	WITNESSED	5-5-71	_	
WITNESSES TO CORNER				
N o	9" Cedar		N 37 W	9.0'
	7" Cedar		S 63 W	2.5'
	AND			
CIRCLE CORNER REGISTERE	D	<del></del>		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by standard survey procedures during a survey of Section 4.

SURVEYOR'S SEAL

DISTRIBUTION:

ENED luill Hisland

5-12-71

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing