## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		OTSEGO		COUNTY	
		T	31 & 32	R_	1 W
DESCRIPTION OF CORNER	E 1/16 corner common	to Secti	ons 4 & 33		
CORNER MONUMENT	Set 1-1/4" Pipe	·		······································	
DATE MONUMENT PLACED AND	WITNESSED	3-	25-71		
WITNESSES TO CORNER	•				
N O	7" Cedar	S	, W		12.6'
	6" Cedar Twin Top	N	W		5.21
	AND				
CIRCLE CORNER REGISTER	ED	<del></del>			<u></u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set MPOL between N 1/4 corner and NE Section Corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

MATE 3-30-1

10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68