## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	OTSEGO COUN		COUNT	Ύ
T	31 & 32	R	1	W

DESCRIPTION OF CORNER	Sec. corner common to Sections 4-5-32-33		
CORNER MONUMENT	Set Dept. Monu	ment	
DATE MONUMENT PLACED AND W	ITNESSED	3-25-71	
VITNESSES TO CORNER	9" Cedar	N 28 W	19.3'
No		•	
5	8" Cedar	N 30 E	24.0
[ <del></del>	6" Cedar	S 86 E	22.41
	AND		
CIRCLE CORNER REGISTERED	)		· · · · · · · · · · · · · · · · · · ·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during retracement survey of Section 4. Old NBTs in place, fits description of old CC C survey notes.

Found 1-3/4" pipe at corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Quiel Stilling REGISTERED LAND SURVEYOR

10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing