APR 2 5 1995

COMMISSION

on this certificate.

REMONUMENTATION COUNTY

LAND CORNER RECORDATION CERTIFICATE

) - 1111111 -	Filing Requirement of Act 74, Mich. P.A. 1970 LINEN U U	ч
or corners in	ALSO Act 345, PA 1990	

OTSEGO COUNTY Otsego Located in: Corner Code ## RECEIVED FOR RECORD T 31 N R 1 W 1 Public Land Survey 94 DEC 29 PM 1:31 ___ R B EVELTH M. PRATT CLERK / REGISTER OF DEEDS R R 2. Property Controlling _ T in Section 2 R _ R _ T ._ Miscellaneous S Register of Deeds Stamp & File Number Property in Sec. Т R __ , Recorded Plat 5 Private Claims . in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

GLO 2/10: J. Mullet, 1840: set Post Sugar 16" S 52°W 15 lks (9.9'), Sugar 8" N 28°E 12 lks (7.9').

CSR 1/107: D.M. Hoffman, 1907: Sugar 16" S 52°W 15 lks (9.9'), Sugar 14"N 20°E 46 lks (30.4'), Sugar 12" S 45°E 42 lks (27.7')- (Ed. First Sugar was GLO, therefore I assumed he found GLO Post).

CSR 3/124: G.F. DeLaMater, 1938 "x36" bar in corner established on Twp. line between corners of which we were sure (A-4 & A-7)-Large Stone N 89°E 51.8', Concrete Monument S 37°W 50.2', Triple W.Birch 4" S 88°W 5.9'. G.F. DeLaMater, 1946: Found 100' error in 1938 work and adjusted corner to new position.

LCRC 2/143: G.R. McKelvey, 1979: Found ½" Iron Rod, W. Birch & Concrete Monument witnesses, set Otsego County Monument-½" Iron Rod S 08°E 74.61', spk 9" Aspen N 37°E 41.09', spk 12" W. Birch S 88°W 5.66', Concrete Monument S 37°W 50.12'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Otsego County Monument and all of McKelvey's witnesses which include DeLaMater's Concrete Monument & triple W. Birch. DeLaMater proportioned this corner between A-4 & A-7, I find it fits this proportion within one foot.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Otsego County Monument-spk 11" Aspen N 37°E 41.09', }" Iron Rod S 08°E 74.61', Concrete Monument S 37°W 50.12',

spk 12" Tri W. Birch S 88°W 5.66'. This corner is accepted as a careful and faithful reestablishment of the p

position of the original corner.

ATE OF MICHIG CARL L ROBINSON OFESSIONAL BURVEYOR OFESSION!

OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1990, 12/22/94. Chairman

Robinson, Otsego County Surveyor 16390 Surveyor's Michigan License No. _

December 15, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1911 REVISED MAY 14, 1975 REVISED JAH., 1913