| × + +, | <u>or</u> | SEGO COUNTY REMONUMENTATION | MBER O O O G. PAULT 25 |
|--|---|--|---|
| For corners in | | RNER RECORDATION CERTIFICAT quirement of Act 74, Mich. P.A. 197 ALSO Act 345, PA 1990 | OTCEOG COUNTY |
| OTSEGO (County) | Located In: | Corner Code =44 | 95 DEC -6 PM 1: 29 |
| Public Land Survey | T 31 N R 3 k t R T R T R | | EVILLY HILPRATT CLERK / REGISTER OF DEEDS |
| Property Controlling in Section Miscellaneous Property in Sec. | | R | egister of Deeds Stamp & File Number |
| I. Carl I. Robinson do hereby certify that unde in lines 1 and 2 above we current manual of survey i Management or by a decre above were in conformanc Court of Law; establishe expressed below: | in a field survey on errequirements of P.A. 74, Michigan re in conformance with regulation instructions of the United States Die of a Court of Law and/or that the rewith the rules of the Michigan Bod, re-established, monumented the Corners, all in the same too. | October 24 19 95 nP.A. of 1970, the corner points mentioned in sand rules therefore as required in the Department of the Interior, Bureau of Land corner points mentioned in lines 3, 4 and 5 pard of Land Surveyors or by a Decree of a re-monumented, recovered, found as with and range, may be recorded | 2 6 5 3 3 2 1 - 3 3 2 1 - 3 3 4 35 36 - 36 - 36 - 36 - 36 - 36 - 36 - 3 |
| GLO 2/283: Austir CSR 1/15: J.M. Sa CSR 2/70: D.M. Ho CSR 2/318: G.F. I MSHD M-32 plans, LCRC 1/43: W.W. W | n Burt, 1850: Set Qr. Sec. anborn, 1882: Sugar 10" N 7 offman, 1902: Pine stump 36 DeLaMater, 1938: Found Iron | es and/or subsequent restoration: Post-Sugar 7" S 38°W 21 lks 13.9', 112°E 64 lks (42.2'), Sugar 8" S 83', "N 68°W 42 lks (27.7') Fence in 1: a-Concrete Monument West 34.0'. ow pavement-Fe.Post West 35.05', 7' con-Concrete Monument west 34.21', 1 | r R.Pine N 55°W 51.50'. |
| | | hod applied in restoring or reestablishin | |
| Errad Obsess Com | oty Monument (tipped) on ce | enterline of bituminous pavement no | rth & south and old fence line |

Found Otsego County Monument (tipped) on centerline of bituminous pavement north & south and Old Tence Inte-to west, DeLaMater's concrete Monument west and two Pine stumps northwest. Removed Otsego County Monument to straighten and found $\frac{1}{2}{}^{\alpha}$ iron rod below monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Reset Otsego County Manument over }" Iron Rod 2'± east of centerline of bituminous pavement north and south, accepted as the best available evidence of the position of the original corner-1" Capped (JLS) Iron rod S 88°E 33.08', PK 11" Cherry S 32°E 63.51', Lag (JLS) S 18°W 106.29', Concrete Monument West 34.10' spk & tag Twin 8" Pine N 64°W 59.30', spk & lag 11" Pine N 42°W 78.27'. STATE OF MICHIG

OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1990.

| Group, pursuant to Act 345, PA 1350. Wate V. Chairman | PROFESSIONAL SURVEYOR NO. 16390 |
|--|---|
| Signed by Date November 15, 1995 | OF ESSIONAL WAR |
| rarl Robinson, PE & PS. Otsedo County Surveyor | TE BOARD OF LAND SURVEYORS, JAN. 24. 1971 Revised May 14. 1915 Revised Jan., 1983 |

CARLI. ROBINSON