OTSEGO COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

ledan erren			,
ALSO Act	345,	PΑ	1990

OTSEGO COUNTY MICHIGAN RECEIVED FOR RECORD

95 DEC -6 PM 1: 29

CLERK / REGISTER OF DEEDS


For corners in Corner Code ## OTSEGO Located In: (County) T 31 NR 3 W 1. Public Land Survey __ R __ R. 2. Property Controlling T ____ R ___ in Section T .____ 8 .___ Miscellaneous Т R Property in Sec.

ON THE PROPERTY OF

Register of Deeds Stamp & File Number

____ , Recorded Plat ___ 5. Private Claims _

October 24 , 19 25 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the Carl I. Robinson _ , in a field survey on ... current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:



NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration.

GLO 2/286: Austin Burt, 1850: Set Qr. Sec. Post-Beech 7" S 23°E 19 lks (12.5'), Beech 6" N 58°W 23 lks (15.2').

CSR 2/22: D.M. Hoffman, 1900: Gov't 8's O.K. CSR 2/318: G.F. DeLaMater, 1938: Found corner 0.K.- Concrete Monument S 45°W 48.0', Concrete Monument N 45°W 48.0'. CSR 3/438: Wm.R. Downey (MSHD), 1959: Found 1" rod-T.Pole S 52°E 50.84', T.Pole S Z2°W 76.43', T.Pole N 20°W 50.84'.

LCRC 1/163: C.I. Robinson, 1972: Found }" Iron Rod in pavement-tag P.Pole S 40°E 51.79', Stop Sign Post S 70°N

53.67'. P.Pole N 40°W 42.85'. LCRC 2/289: J.L. Schwandt, 1982: Found 1/2" bar and all Robinson's references, set Otsego County Monument- P.Pole S 40°E 51.79', Stop Sign Fost S 70°W 53.67', Concrete Monument N 45°W 48.78', P.Pole N 40°W 42.85'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Otsego County Monument at surface and intersection of centerlines of bituminous pavements, DeLaMater's Concrete Monument (bent) northwest, subdivision monument southwest and all of Robinson's & Schwandt's refereces.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Otsego County Monument at intersection of centerlines of bituminous pavements, accepted as a careful and faithful perpetuation of the position of the original corner-tag (#16390) P. Pole S 50°E 52.05', tag (#26466) P.Pole 5 40°W 41.39', Concrete Monument S 45°W 46.81', tag (#16390) P.Pole N 40°W 42.62'.

E OF MICHION CARLI ROBINSON PROFESSIONAL SURVEYOR No. 16390 POFESSION W. FESSION Date

OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Pear Group, pursuant to Act 345, PA 1990. V. Chairman

Signed by Carl I. Robinson, PE & PS, Otsego County Surveyor Surveyor's Michigan License No. 16390

November 15, 1995

FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, SAM. 28, 1971 REVISED MAY 14, 1975 REVISED JAM., 1983