OTSEGO COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

LIBER OOO4 PAGE 134

OTSEGO COUNTY

Filing Requirement of Act 74, Mich. P.A. 1970 ALSO A ct 345, PA 1990

For corners in

MICHIGAN RECEIVED FOR RECORD Corner Code ## Located In: OTSEGO 95 DEC -6 PH 1:30 131 N R 3 W G-11 1. Public Land Survey ____ R __ LYLLYIGH PRATT CLERK / REGISTER OF DEEDS R 2. Property Controlling _ 8 _ ... R _ S in Section R Miscellaneous s T Register of Deeds Stamp & File Number Property in Sec. s _ R . _ , Recorded Plat _ 5 Private Claims _ October 26 19 95 Carl I. Robinson , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: GLO 2/277: Austin Burt, 1850: Set Post-Sugar 14" S 66°E 32 1ks (21.1'), Beech 8" N 64°W 11 1ks (7.3'). CSR 2/22: D.M. Hoffman, 1900: Gov't B's U.K. CSR 2/322: G.F. DeLaMater, 1936: ½"x30" bar in Monument Box (placed by MSHD)-Concrete Monument N 71°E 100.0', Concrete Monument S 70°E 100.0'. LCRC 1/47: W.W. Wakenbut, 1972: Found ½" iron in Monument Box & DeLaMater's Monument NE-Concrete Monument N 80°E 99.89', spk P.Polc N 45°E 103.53', spk 12" Maple N 15°W 108.65'. LCRC 1/163: C.I. Robinson, 1972: Found 1" iron in Monument Box at approximate intersection of pavement centerlinestag 20" Elm S 24°E 73.20', tag P.Pole N 56°W 117.21', tag 12" S.Maple N 22°W 108.60'. NOTE: Corner & witnesses used in numerous surveys by several different Surveyors in the past 23 years. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found ½" Iron Rod (9" deep) in Monument Box at Intersection of pavement centerlines north-south & east-west, DeLaMater's Concrete Monument NE, Wakenhut's P.Pole NE and Robinson's P.Pole NW. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner; Raised ½" Iron Rod with capped ½" Iron Pipe in Monument Box at intersection of pavement centerlines north-south & east-west, accepted as a careful and faithful perpetuation of the position of the original corner-spk P.Pole N 53°E 106.47', Concrete Monument N 70°E 100.15', spk P.Pole S 67°W 90.87', tag (#16390) P.Pole N 50°W 116.98'. NE OF MICHIGA OTSEGO COUNTY REMONUMENTATION Approved by the County Survey Peer ROBINSON Group, pursuant to Act 345, PA 1990.

Date

V. Chairman OFESSIONAL SURVEYOR No. 16390 OFESSIONS ANTHON THE PARTY NAMED IN November 21, 1995 Signed by Carl I. Robinson, PE & PS, Otsego County Surveyor Surveyor's Michigan License No. 16390 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAH., 1983