## 

## OTSEGO COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBEROOOL PAGE 136

OTSEGO COUNTY

For corners in		ALSO Act 345, PA 1990		RECEIVED FOR RECORD
	. OTSEGO	Located In:	Corner Code ##	HEACT CALL COMP
	(County)			95 DEC -6 PM 1:30
1	Public Land Survey	T 31 N R _3 W	H-10	Product of the Control of the Product of the Control of the Contro
• •	1 oblic Edild Colley	T R		EVLEYN M. PRATT CLERK / REGISTER OF DEEDS
		T R		THE RESIDENCE OF SECTION
		T R		
2.	Property Controlling	S T R		
	in Section	S T R		
3.	Miscellaneous	S		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		
				3 4 7 8 9 10 -11 12-
I	Carl I. Robinson	in a field survey on	0000001 27 19 22	5
do	hereby certify that under requ	uirements of P.A. 74, Michigan P.A. conformance with regulations an	the 6 18 17 16 15 14 13-	
-	grant manual of survey instruc	ctions of the United States Depar	and '	
M	anagement or by a decree of a (	Court of Law and/or that the come	nd 5 8 19 20 21 22 22 23 24	
ab	oove were in conformance with	the rules of the Michigan Board of	f as 9	
Court of Law; established, re-established, monumented, re-monumented, recovered, for expressed below:				10 30 29 28 25
	•	rners, all in the same town a	nd range, may be recorded	11
•••	on this certificate.	•		12 31 32 33 34 35 36
				13

A. Description of original monument and accessories and/or subsequent restoration:

CSR 3/98: G.F. DeLaMater, undated: Concrete Monument placed by guess on our north & south (1) line by survey party working on Sanitarium Survey, 2609' north of 1 (7). (Ed. State crew used incorrect procedure).

LCRC 2/170: C.I. Robinson, 1980: Set Otsego County Monument at the intersection of 1 lines-spk P.Pole N 25°E 90.61', steel Fence Post S 60°E 35.19', 3/4" iron pipe in Concrete Monument S 3°E 1.52', spk Corner Fence Post S 87°W 34.57'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Otsego County Monument 3'± west of centerline graded road, broken Concrete Monument south 1½'±, P.Pole NE, and Fe.Post SE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Otsego County Monument 6" deep and 3'± west of centerline graded road, this position was not established by original government surveyors, this monument is accepted as the best available evidence of the position of the corner-spk P.Pole N 23°E 90.42', 23" Steel Gate Post N 59°E 40.15', 2" capped Iron Rod N 88°W 32.50', 1"x34" E OF MICHIG Orange Top Pipe N 48°W 29.60'.

CARLI. ROBINSON ROFESSIONAL SURVEYOR 16390 OFESSION?

Date

OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1990.

November 21, 1995

Signed by . County Surveyor Carl I. Robinson, PE & PS, Surveyor's Michigan License No. 16390

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1943