CURVEYS REMONUMENTATION

## OTSEGO COUNTY REMONUMENTATION

MAY 28 1997

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970
ALSO Act 345, 1990

ALSO Act 345, 1990  OTSEGO Located In:	19/0
Located In: Corner Code #  1. Public Land Survey  T31NR 4 W I-12 TR	OTSEGO COUNTY MICHIGAN RECEIVED FOR RECORD
2. Property Controlling S T R S S T R	96 DEC 30 PM 2: 19  EVELYA M. PRATT CLERK / REGISTER OF DEEDS
Property in Sec. STR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	The Hampi
5. Private Claims	A B C D E F G H 1 J K L
I, <u>Carl I. Robinson</u> , in a field survey on <u>December 16</u> , 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the <u>corner points mentioned in lines 1</u> and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	3 4 - 7 - 8 - 9 - 10 - 11 - 12 5 - 6 - 18 - 17 - 16 - 15 - 14 - 13 7
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
A. Description of original monument and accessories and/or subsequent restoration: GLO 2/397: Austin Burt, 1850: Set Qr. Section Post-Sugar 10" S 69°E 20 1ks (1 CSR 1/40: J.M. Sanborn, 1889: Sugar 20" N 70°E 63 1ks (41.6'), Sugar 10" S 33 Sugar 10" S 69°E 20 1ks (13.2'), Sugar 12" N 74°W 29 1ks (19.1'). CSR 1/75: A.W. Bates, 1893 or 94: Found Gov't B & P-Sugar 20" N 72°E 63 1ks (4 CSR 3/464: S.O. Thorsen, 1959: Placed ½" Bar-T.Maple S 81°E 68.5', R.Pine 10" Survey 510/891: J.L. Schwandt, 1992: Found ½" Bar-8" Maple N 80°E 51.9', 8" Ma 84.3', 4" Maple N 40°W 65.85'.	*E 429 1KS (28.7'). Hoffman, undated: 41.6'), Sugar 14" S 290F 431 1kg (28.7
Description of corner evidence found and/or method applied in restoring or reestablishing corner Found ½" Iron Rod 2.8'± west of pavement centerline Thorsen's Maple east, both southwest. Traverse measurements north & south indicate Thorsen placed this coint in incorrectly placed corner north and the correct I-13. If placed at the correct would be 2.8' north & 1.9' east, but many surveys and two subdivisions have in the past 38 years. There is no reason to assume that a corrected location with the past 38 years.	Schwandt's Maples east & R.Pine rner single proportional between
ROBINSON X	the best available evidence of the igher in tree), Face of blazed 11", MDOT tag 12" R.Pine S 65°W 82.32',  SEGO COUNTY REMONUMENTATION  Peroved by the County Survey Page
The serious of Description of the serious of the se	oup, pursuant to Act 345, PA 1990.  20 (996 V. Chairman
ed by Or Ession A way	19, 1996

The state of the s