SURVEY & REMONUMENTATION

APR 2 5 1995

OTSEGO COUNTY REMONUMENTATION

Filin

D CORNER RECORDATION CERTIFICATE	TIMER OF FILL IA	TAULU -	
g Requirement of Act 74, Mich. P.A. 1970	Libra O O o	,	
ALSO Act 345 PA 1990	A***	~ ~ ~ ~ ~ ~	

FOCOMMISSION OTSEGO ICOUNTY)		ALS	50 Act 345. PA 1990	OTERRO COUNTY	
		Located In:	Corner Code ##	HICHIGAN RECEIVED FOR RECORD	CHIGAN D FOR RECORD
1.	Public Land Survey	T 31 N R 2 W		94 DEC 29 PN 1: 34	
		T R T B		LYELTH M. PRAIT CLERK / REGISTER OF DEEDS	
2.	Property Controlling in Section	S T R S T R	l.		
3.		S T R S T R		Register of Deeds Stamp & File Number	
				A B C D E F G H I J K L	
5.	Private Claims			2 6 5 4 3 2	ŗ
	Carl I Robinson i	n a field sunsay on	December 19 ₁₉ 94	4 7 8 9 10 11	12
do in l	hereby certify that under requir lines 1 and 2 above were in or	rements of P.A. 74, Michigan P.a onformance with regulations a	A. of 1970, the corner points mentio and rules therefore as required in artment of the Interior, Bureau of L	oned 6 18 17 16 15 14 1	13
			artment of the interior, bureau of L ner points mentioned in lines 3, 4 ar		

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

nicen # 0

A. Description of original monument and accessories and/or subsequent restoration:

GLO 2/10: J. Mullett, 1840: Post-Pine 14" S 47°W 06 lks (4.0'), Tamarack 10" N 47 E 03 lks (2.0').

CSR 3/124: G.F. DeLaMater, 1938: Found one Gov't B & P, ½"x36" iron in corner- W. Pine stump 14" N 34°E 42.3', W. Pine stump 18" N 47½°W 68.1'. Conservation Department, 1951: 1" Pipe w/4" brass cap-Cedar 8" N 78°E 53 lks (35.0'), R. Pine stump 18" N 55°W 9 lks (5.9').

LCRC 2/143: G.R. McKelvey, 1979: Found DNR monument & prio CSR witnesses-1" Iorn Rod S 85°E 19.18', spk ?" Spruce S 23°W 22.20', spk Fe. Post North 24.33', spk Fe. Post West 16.74'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found DNR Monument 0.5' northeast of fence corner post, both DeLaMater's W. Pine stumps, Conservation Department's Cedar, McKelvey's fence post West & $\frac{1}{2}$ " iron rod East.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR Monument 0.5' northeast of fence corner post is accepted as a careful and faithful perpetuation of the position of the original corner, nail 14" R. Pine N 46°E 74.90', nail 12" Cedar N 78°E 35.68', nail 9" Cedar

S 39°E 49.95', nail 8" Cedar N 24°W 57.38'.



OTSEGO COUNTY BENCHWIENTATION

Approved by the County Survey Pear Group, pursuant to Act 345, PA 1990. Chairman Date

Signed by	\subseteq	لم کا ہم	(_			
Signed by	Carl I.	Robinson,	PE	& PS,	Otsego	County	Surveyor
Surveyor's	Michigan l	icense No.		16390			

December 20, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983