# SUMULA OR REMONUMENTATION

APR 2 5 1995

on this certificate.

### OTSEGO COUNTY REMONUMENTATION

#### LAND CORNER RECORDATION CERTIFICATE

#### FOCOMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 0 4 PAGE 0 6 3

	***************************************			หตวก	1 ACL 343, PA 1990	Pinner C	, , ,	•	•							
	OTSEGO (County)	<del></del>	Located In	:	Corner Code ##	1			~~ ~	C 2 4						
1.	Public Land Survey	T 31 N R 2 W		M-11	OTSEGO COUNTY MICHIGAN RECEIVE TO RECORD											
			T T	R				94	DEC	29	119		: 35	r		
2.	Property Controlling in Section	_	T   T				CLEAR / REGISTER OF DEEDS									
3.	Miscellaneous Property in Sec.		T ! T !			Re	gister	gister of Deeds Stamp & File N							r	_
4.	Lot No ,	Recorded	i Plat					B	Ç E	1 £	F (	3 L	4 1			
5.	Private Claims						- 2 3	- 6-	Ĭ-5	Ī			Ì	, 2 2	Ì	_
I. Carl I. Robinson , in a field survey on December 21 , 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned										+	-  -	~\ -\	<b></b>	  -111	2 	_
in l	lines 1 and 2 above were rrent manual of survey ins	in conform	nance with reg I the United St	ulations an ates Depart	d rules therefore as required tment of the Interior, Bureau or r points mentioned in lines 3,	I in the of Land	7	-18 	十 <sup>17</sup>	<del>-</del>	16	—15 —	<del>-</del>		— 13 — }	_
abo Co	ove were in conformance v	with the rule	es of the Michi	gan Board o	of Land Surveyors or by a Deci nonumented, recovered, fou	ree of a	9	-19	$+\tilde{1}$	+	21-	22 27	-	23-23-26-	-24 	_

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

CLO 2/8 & 9: J. Mullett, 1840: Set Post-Beech 14' N 2°E 21 lks (13.9'), Sugar 10" S 29°W 13 lks (8.6'). CSR 2/260: G.F. DeLaMater, 1925: Found one Gov't B. & P., set 1"x30" Bar-Stone N 43°W 51.4', Elm 4" S 74°E 21.6'. Concrete Monument S 43°E 51.7' added later. (Note: OCRC set monument box per 1967 Construction Plans).

LCRC 2/62: G.R. McKelvey, 1977: Found 1" Iron Rod in Mon Box and Concrete Monument S 43°E 53.74', NE Corner Fr. Garage S 40°W 119.40', NE Corner of Chimney on Cabin S 37°E 104.0', nail P. Pole N 51°E 47.38'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" Iron Rod in Monument Box 0.5'± south of pavement centerline and on approximate centerline of gravel road north & south, DeLaMater's concrete monument, and all McKelvey's witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" Iron Rod in Monument Box 0.5'± south of pavement centerline and on approximate centerline of gravel road north & south, and is accepted as a careful and faithful perpetuation of the position of the original cornerspk P. Pole N 51°E 48.18', Concrete Monument S 43°E 53.71', NE corner of Chimney on Cabin S 37°E 104.04',

2" Capped Iron Rod S 53°W 46.89'. ½" Capped Iron Rod S 53°W 46.89'.

THE OF MICHIGA CARLI ROFESSIONAL SURVEYOR 16390 OFESSIONA WANTESSION N

## OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1990. 2294 Chairman

Otsego County Surveyor

Carl I. Robinson, PE & PS, Surveyor's Michigan License No. 16390

December 21, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983