

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 32 N.R. 1 W
T. 33 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 1-2-35-36

CORNER MONUMENT Left 1½" pipe in place

DATE MONUMENT PLACED AND WITNESSED 5-3-67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

5" H. Maple S 39 E 37.9'

9" Basswood N 38 W 22.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this area. Found 1½" pipe with concrete base at corner as previously established by Marcus Schaaf, R.L.S. in survey during 1930's. Best available evidence.

SURVEYOR'S SEAL

SIGNED _____ DATE 5-24-67

REGISTERED LAND SURVEYOR

#10068