MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_32_ NR_1_1_

			Otsego COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between sections 26 & 35
DESCRIPTION	OF	CORNER	MONUMENT 1" Iron Pipe with 4" Brass cap
WIT TNESSES	то	CORNER	8* Cedar - S 75 E - 20 Links
			7 Cedar - S 44 T - 8 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was previously located and perpetuated by Mercus Schaaf, Registered Land Surveyor, from original 3.T.'s. Two original B.T.'s still in place, in good condition.

Corner was placed and witnessed December 12, 1950.

SURVEYORS SEAL

SIGNED DATE 12/22/50
REGISTERED LAND SURVEYOR