



OTSEGO COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Also Act 345, PA 1990

OTSEGO COUNTY MICHIGAN RECEIVED FOR RECORD

For corners	in
-------------	----

5. Private Claims

Located In: Corner Code # Otsego Corwith Township (County) 1. Public Land Survey T<u>32N</u> R<u>2W</u> I-9 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

_, Recorded Plat _

00 JAN 10 AM 10: 10

EVELYN M. PRATT CLERK / REGISTER OF DEEDS

Register of Deeds Stamp & File Number

Schwandt , in a field survey on Jan. 19 , 19 99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 6 11
- A. Description of original monument and accessories and/or subsequent restoration:
- I-9, T32N-R2W G.L.O. John Mullett June 21, 1850 Set Maple post Y. Pine, 15", N52°W, 18 links (11.88') Aspen 15", S26°E, 9 links (5.94')
- Delamater, 1931 1/2" X 30" bar in corner Found one Gov't B, plainly marked Y. Pine 10", S66°W, 151.0' Y. Pine, 5", N66°E, 102.9'
- Carl I, Robinson, 1980 Fnd 1/2" iron in corner Set Otsego County Mon. Set spk 12" Pine, N66°E, 103.71' Set spk 7" Aspen, N05°E, 19.60' Set spk 4" W. Pine, N35°E, 28.79' Set spk, fence post, South 5.95'
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Otsego County Monument Fence post, South, +/- 6'

OF MICHIO JAMES L SCHWANDT PROFESSIONAL SURVEYOR No. 26466 C. Description of monument for corner and accessories established to perpetuate locating the position of the BESSION!

Otsego County Monument in corner and is accepted as a careful and faithful perpetuation of the position of the original corner.

10" Twin W. Pine, S40°E, 10.34

10" R. Pine, N22°W, 42.71' 10" W. Pine, N88°W, 46.32" 6" W. Pine, S05°W, 31.04'

Surveyor's Michigan License No.

OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1999

1999 Date

Chairman

Signed by

26466

Date 12-28-99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197 REVISED MAY 14,197

REVISED JAN., 198 REVISED OCT., 199

Liber 4, Page 236