SURVEY & REMONUMENTATION

APR 2 4 1995

4. Lot No.

5. Private Claims ___

COMMISSION

Ottawa County Remonumentation LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED


94 DEC 15 AM 11: 49

For corners in		v milg stequillening to the training the training to the train		Phythis Callenan
	Ottawa (County)	Located In:	Corner Code ##	REGISTER OF DEEDS OTTAWA COUNTY.MI
1.	Public Land Survey	T <u>5N</u> R <u>14W</u> T R T R T R	K-3 (SE, 2) Zeeland Twp.	
2.	Property Controlling in Section	S T R S T R	<u> </u>	
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

John C. Bueche, in a field survey on <u>December 7</u>, 19 <u>94</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

__ , Recorded Plat __

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

K-3 GLO, March,			LCRC L -P
1832	3/4" iron, Sept.,	T iron, March,	T iron, Feb., 1983
Calvin Britain,	1973	1980	PK in SE PP SW 69.60'
D.S.	PP SW 59.51'	PK on PP SW 69.59	'PK in NE TP SE 64.48'
Set cor.	St. sign	PK on TP SE 64.5'	PK in NW PP NE 64.64'
Sugar 7	WSW 28.89'	PK on TP NE 64.6'	Iron SSE 11.90'
S 56 W 7	Cor. fe. post	C/L st. sign	
Beech 7	SE 38.66'	SW 34.02	,
N 56 E 20	Cor. fe. post	Iron SSE 11.85	,

B. Description of corner evidence found and 8 method applied in restoring or reestablishing corner:

K-3 Found T iron down 1.5'+

As per above wit.

And is accepted as a careful and faithful perpetuation of the position of the original corner.

P.A. 345 OTTAWA COUNTY
PEER APPROVED 12 12 94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-3 Left T iron in place & set Ottawa Co. Mon. (3/4" x 24" Pin with Alum Cap) down 8"

Nail & Ottawa Co. Remon. Tag in SE side PP S 35 W 69.33'

Nail & Ottawa Co. Remon. Tag in W side PP N 40 E 65.04'

Nail & Ottawa Co. Remon. Tag in E side PP N 05 W 298.71'

NE cor. frame bldg.

On C/L gravel rd. N-S

Iron

SSE 11.90'

C/L gravel E, S 8'+

Signed by John C. Bueche Surveyor's Michigan License No. 13027

SURVEYOR
No.
13027
PLANT SURVEYORS.

JOHN C. BUECHE

LAND

LAN TRE