## **OTTAWA COUNTY REMONUMENTATION**

			ECORDATION CER t of Act 74, Mich. F								-,	
For corners in	Located In:	Corner Code #		i	RECORDED							
(County)					•							
1. Public Land Survey	T_5N R_15W	_	E-10		96 DEC 20 PM I2: 20							
	TR T R		East 1/4 corner Section 29		REGISTER OF DEFINE							
2. Property Controlling S	TR TR	_	Holland Twp.		REGISTER OF DEEDS OTTAWA COUNTY, MI							
in Section S  3. Miscellaneous S	TR TR			Regi	Register of Deeds Stamp & File Number							
Property in Sec. S	TR	_								<del></del>	<u>-</u>	
<ol> <li>Lot No, Recorded I</li> <li>Private Claims</li> </ol>	Plat				1 A	В (	C D 1	E F (	<b>∋</b> H (	JK	L	
					2	φ	5	4	3	-2	·	
I, Steven Lampen	, in a field su	rvey on	December 6 19 9	96	4	7	-8	<b>.</b> q.	10	- 11	- 12	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land						18	17	16	15	14	13	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					6 7 -		ļ- <del>, ,</del>					
Court of Law; established, re-establi expressed below:					8	19	20	-21	-22	23	24	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					10	30	29	28	27	26	25	
						-31	32	33	34	35	36	
A. Description of original monun		s and/or	r subsequent restoration	on:	13 L		Li		<u> </u>	L	<u></u>	
GLO-Brookfield-1832 Set 1/2 mile post Beech 10 N24W 20	P.P. SW	45.65 47.85 49.98 45.63						•				
			·									
B. Description of corner evidence	e found and/or met	hod app	lied in restoring or ree:	stablishing (	corne	er:						
E-10 Found iron pipe over F Lincoln Ave. This corner fit Subdivision of Block A, A.C. also agrees with section mea	s the monumentati Van Raalte Addit	ion of t	the plats of the Or: . 1, and Riverside A	iginal Pla	t of	Holl	land,	di.				
Replaced iron pipe and steel a careful and faithful perpe					and	isa	ecept	ed as				
				P.A. 345	077	raw	A CO	UNT	Y			
			,	APPROV	_ 	l,	12	11.	1			
C. Description of monument for	corner and accesso	ories est		_				-				
E-10 Ottawa County Remonumer			. ,	, , , , , , , , , , , , , , , , , , ,	. С ро	5,2,5,	371111	niin <sub>es</sub> N 40	Inning	<i>,</i>		
Azimuth = Michigan State Pla NE corner building, brick	:	215°42′	103.25			111	of the	STEVE	··.'/6 <sub>.0</sub> /	The state of		
SE corner depot, brick, 4' a		50°59'	319.62			THE STATE OF	<b>*</b>	LAMPI	EN	X.E	•	
SW corner depot, brick, 4' a NW corner building, brick, 4		46°36′ 103°25′	315.14 175.56			Ξ		LAN	) (0)		7,00	
SW corner building, brick	_	130°06′	221.56			## T	<u>.</u>	URVE' No.	iUK	: 05 E		
NW corner building, brick		171°14′	236.05			1	٠٠)	3727	9 .	公義		
SE corner building, brick	:	290°12′	151.09			7	MA EN		زراه	高。	LOKALK.	
							Mill	unnin V LAN	mann.	<i>,</i> •.		

Signed by Steven Lampen

37279

Surveyor's Michigan License No.

Date DECEMBER 13, 1996

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1976 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993