OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

RECORDED

Filing Requirement of Act 74, Mich. P.A. 1970

97 JUL 24 PM 2: 23

For corners in Ottawa (County)	Located in:	Corner Code	#	·Q	# RE	EGIST	ER OF I	DEEDS	m)	
Public Land Survey Property Controlling S in Section S	TR TR TR TR	F-1 N 1/4 corn. S Park Twp.	Sec. 4							
3. Miscellaneous S Property in Sec. S	TR TR		····	Register	of De	eds S	tamp	& File	Numbe	er ·
4. Lot No, Recorded Plat 5. Private Claims				- , A	B C	D	E F (Э Н !	JK	L N
				2 3	6	5	4	3	2	1
I, Steven Lampen in a field survey on December 6, 1996 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corne in lines 1 and 2 above were in conformance with regulations and rules therefore			points mentioned	4	7	8	9	10	11	12
current manual of survey instructions of the United States Department of the Interior, Bureau of Lan Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of				6 7 -	18	17	16	15	14	13
Court of Law; established, re-est expressed below:	tablished, monumented, re-monumented	mented, recove	ered, found as	8	19	20	21	22	23	24
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			recorded	10 11	30	29	28	27	26	25
A. Description of original monument and accessories and/or subseque			t restoration:	12	31	32	33	34	35	36
GLO - corner not set by original from the set of the se	ginal GLO Survey									
Survey in Liber 5, Page 183 Found concrete monument Port	- 1982 t Sheldon corner E 95.27'									-
B. Description of corner evide	ence found and/or method app	olied in restor	ing or reestablishi	ng corne	r:					
Found concrete monument Port	Sheldon corner E 95.27'									•
This corner not monumented be evidence of the position of	by the original GLO Survey the corner.	. This mon	ument is accepte	ed as th	e bes	t ava	ilabl	*		
Found concrete monument on t Remonumentation iron and cap	the South line of Section o in a (set) monument box.	33, T6N, R1	6W, and replaced	i it wit	h an	Ottaw	ra Coui	nty		
	PA. 345 OTT	L 345 OTTAWA COUNTY								
PEE			RAPPROVED 12:9-96							
				G.	D.	ラシ	7	•		
C. Description of monument t	for corner and accessories est	tablished to p	erpetuate locating	the pos	ition o	f the	corner	;		
0ttawa County Remonumentatio	on iron and cap in monumen	t box. Azim	uth = Michigan S	State Pl	an gr	id di	rection	Muun Muun	.	
F-13, T6N, R16W = iron in mo	onument box	88° 2	24' 95.27'			,ii	MATE	OF MIL	HIE	ie.
Remon. tag in North side 16"	Beech	148° 2 251° !	22' 28.28' 55' 60.10'			N. S.	۶.۰.۶	TEVEN	10	
Remon. tag in East side 22" Remon. tag in East side 12"	Oak Pine	348° 3	15' 32.68'			13 E E	<i>:</i> L	AMPEI	۱ ۱)
Centerline E and W asphalt r	coad pavement	0.0	0'			Ĭ ,	SU	RVEY	R .	, E
C. Description of monument of F-1 Ottawa County Remonumentation F-13, T6N, R16W = iron in money Remon. tag in NE side 14" Pi Remon. tag in North side 16" Remon. tag in East side 22" Remon. tag in East side 12" Centerline E and W asphalt r Centerline N and S asphalt r	oad pavement (Lakeshore A	ve.) 88° :	95.271			AEU:		NO. 37279	· inic	Hammannan Hamman
Signed by Steven Lame			ate <u>dece</u> mbe			,	Vinishin	LAND	Milling 20	
Surveyor's Michigan License No.		L			, । १ १					-
Carryon o imorngan Election No.	. 0,2,0		FORM AF	PROVED BY M	ICHIGAN S	STATE BO	ARD OF LA	ND SURVEY	ORS, JAN.	28, 1971