

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Dorothy R. Anderson
REGISTER OF DEEDS
OTTAWA COUNTY, MI

For corners in
Ottawa

(County)

Located In:

Corner Code ##

| | | | | | |
|------------------------------------|---|----|---|-----|--------------------|
| 1. Public Land Survey | T | 5N | R | 16W | G-8 (W 1/4 Sec 22) |
| | T | | R | | Park Twp. |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous Property in Sec. | S | | T | R | |
| | S | | T | R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, David R. Greer, in a field survey on October 8, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
Recorded in Liber 1 Page 293, March 8, 1972
Recorded in Liber 2 Page 733, Jan. 14, 1975

| | | | | | | | |
|-----|---|----|--------|-----|----------------|----|--------|
| G-8 | Found Cross & Set Iron Pipe in Cross on Concrete Pavement | | | G-8 | Found Iron Bar | | |
| | Nail in face of 12" Maple | SW | 61.05' | | Power Pole | NW | 37.87' |
| | Nail in face of 16" Maple | NW | 77.64' | | Support Pole | SE | 45.00' |
| | Nail in 18" Maple | NE | 81.00' | | 18" Maple | NE | 48.77' |
| | SW Cor Stone Wall | NE | 99.56' | | | | |
| | Exp. Joint | W | 21.10' | | | | |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

| | | | | | | | |
|-----|--|----|--------|--------------|----|--------|--|
| G-8 | Found cast iron monument and accepted it as a careful and faithful perpetuation of the position of the original corner | | | | | | |
| | Nail in face of 12" Maple | SW | 61.05' | Power Pole | NW | 37.87' | |
| | Nail in face of 16" Maple | NW | 77.64' | Support Pole | SE | 45.00' | |
| | Nail in face of 18" Maple | NE | 81.00' | 18" Maple | NE | 48.77' | |
| | SW Cor Stone Wall | NE | 99.56' | | | | |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| | | | | | | | |
|-----|---|--|--|-----|---------|---------|--|
| G-8 | Found C.I.M. in monument box. Set O.C. Remonumentation Iron & Cap | | | | | | |
| AZ | Michigan State Grid Direction | | | | | | |
| | NE Cor School, Brick | | | AZ. | 221°56' | 122.68 | |
| | NE Cor Garage Foundation | | | AZ. | 128°24' | 124.91' | |
| | CL Top Hydrant | | | AZ. | 36°02' | 52.47' | |
| | O.C. Remon tag & nail in SW Side 26" Maple | | | AZ. | 309°25' | 90.72' | |



Signed by David R. Greer
Surveyor's Michigan License No. 16042

Date 10/8/93