## SURVEY & REMONUMENTATION

APR 2 4 1995

## OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 14 MM 9: 42

Dhystai Radiman

COMMISSION For corners in

	Ottawa County	Located In:	Corner	Code ##	1	I	REGISTER OTTAWA C	OF DEEDS	}	
		<b></b>								
1.	Public Land Survey	T _5N_R 16V T R		-W1/4-C	I .					
		TR	060 2	27 ·····						
		T R		Twp.	_   '					
2.	Property Controlling	S T R			_					
	in Section	S T R			_					
3.	Miscellaneous	S T R			_	Register of De	eds Stamp	& File Nu	mber	
	Property in Sec.	S T R			_	<u> </u>			<del></del>	
4.	Lot No,	Recorded Plat				— АВ (	0 E F	в н І	JKL	
5.	Private Claims					— <u> </u>		T	$\sqcap$	
						2 - 6 -	5- <b> 4</b>	13-1-	2-	
						3		++	<del>                                     </del>	
		-				4 - 7 - 1	ė <del>-</del> ė	<del></del>	11-1-	
1, _	John P. Clapp	in a field survey onequirements of P.A. 74, Michigan	November 1	8 19	94	. 5	<del></del>	++-	+ +	
		in conformance with regulations					1716	15	14	
cur	rent manual of survey inst	ructions of the United States De	partment of the li	nterior, Bure	eau of Land	d 7		+	+-	
		f a Court of Law and/or that the co					2021~	22	23	
abo Cor	ove were in conformance would of I aw established.	vith the rules of the Michigan Boa re-established, monumented,	rd of Land Survey re-monumented	yors or by a recovered	Decree or a	a 9		╌┼╌┼╌	+-	
	pressed below:				,	10 -30-	2928	27	26	
NC	TE: Not more than 4	corners, all in the same tow	n and range, ma	ay be reco	rded	11		╀╌┼╌┼╌	+	
	on this certificate	).				1231	3233_		35	
A.	Description of origina	I monument and accessories	and/or subseq	uent resto	ration:	13		1		
	G-10 Govt La	nd Office Survey Notes	G-10 Record	ded in Lil	ber 1	G-10 Rec. in		_		
	•			Page 127, Oct. 22, 1971 Page 365, May 11, 1972						
	Set Post		Set Cast Iro			Fd Cast Iron				
	10" Beech Na	42 °W 23 links	in place of C	Conc. Mo			NNW			
	10" Beech S	35 °E 15 links	Power Pole	W		Power Pole		16.14'		
			30" Maple	NW-		30" Maple		26.57'		
			30" Maple	NNW		24" Beech		61.50'		
			24" Beech	ENE		18" Beech	SE	57.55'		
		•	18" Beech	SE	57.55'					
В.	Description of corner	evidence found and/or meth	od applied in re	storing or	reestabli	shing corner:		•		
	G-10			•						
		on monument and accep	ted it as a ca	reful and	faithful	perpetuation				
	•	of the original corner	•							
	Found Nail &	Tag in NW Side 22" Bee	cn	AZ 14	12°	57.52'				
						P.A. 345 OTT	AWA CO	INTY		
			,		_		12//	194	/	
	•		•		reen /	APPROVED_	104/10	2//	<del></del>	
				•		11		<i>191</i>	1	
						bedoy D.	Todas.	yat billa		
C.	Description of monun	nent for corner and accessor	es established	to perpetu	uate locat	ing the position	of the corn	er:		
	G-10									
	Cast Iron Mor	nument								
	- · · ·	Tag & Nail SE Side 18" I	Beech	AZ.	46°	72.97	7'			
		Tag & Nail SW Side 22"			40  42°	58 2				

Signed by <u>John P. Clapp</u>
Surveyor's Michigan License No.

14091

O.C. Remon Tag & Nail SE Side 12" Pine

O.C. Remon Tag & Nail NE Side Power Pole

Date Dec 5, 1994

LAND SURVEYOR NO. 14091

CLAPP

FORM APPROVED BY MICHIGAN STA

78.72'

59.64'

14091 PLAND BUSEPMAY 14, 1975 FD LAND BUSEPMAY 14, 1975 VISED JAN., 1983

227°

319°

AZ.