

APR 2 4 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 14 AM 10: 03

Phyllin Carlinan

For corners in				,			REGISTER OF DEEDS		
	Ottawa (County)	Located In:	Corner	r Code ≠≠		<i>17</i>	OTTAWA COUNTY	'.Mi	
1.	Public Land Survey	T5N R _16\\ T R T R T R	— Parl	(W1/4 C k-Twp.		2)			
2.	Property Controlling	S T R			_				
_	in Section Miscellaneous	S T R							
	Property in Sec.	S T R S T R			-	Register of Dec	eds Stamp & File	Number	
	Troporty in odo.	, <u></u> ,,,							
4.	Lot No , F	Recorded Plat				A B C	DEFGH	IJKL	
5.	Private Claims	,			, , ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, 		TITI		
						3 3	-543-	1 1	
						4			
I	John P. Clapp	, in a field survey on	November	28	94	5 1	-8-19-10-		
doh in li	nereby certify that under red hes 1 and 2 above were it	quirements of P.A. 74, Michigan n conformance with regulation ructions of the United States De	P.A. of 1970, the c s and rules there	comer point efore as req	smentioned uired in the	° 18 -	-171615	14-13	
		a Court of Law and/or that the co					20 21 22	23 24	
		ith the rules of the Michigan Boa re-established, monumented,							
	irt of Law; established, i ressed below:	re-established, monumented,	re-monumented	, recovered	i, found as	10 30	29 28 27	26——25	
NO.	TE: Not more than 4 c	corners, all in the same tow	n and range, m	av be rece	orded	11			
	on this certificate.					12 31	_323334	35 36	
	B. Adv. & Autural					13			
A.	K-4	monument and accessories	and/or subseq	luent resto	ration:	V 4			
		K-4 fice Survey Notes Reco	rded in Liber	4		K-4 Recorded in I	lihar 5		
		or, Calvin Britain Page				Page 142 Jul			
						Fd Iron Pipe	,		
		N12°E 17 links 6" Oa	•	5°W157.	59'	Set Cast Iron	Monument		
		S18°W 25 links P. Po		49.94		Power Pole	SE 50.33	,	
		ide for additional P. Po				Power Pole	SW 69.34		
	recordings (Lil	ber 5, Page 275) 14" O		0°W90.80		20" Oak	WNW 91.47		
	, ,	CL St	Sian N80	0°E 23.22	2'	7" Poplar	NW 76.47		
3.	Description of corner e	evidence found and/or meth-	od applied in re	estoring or	reestablis	hing corner:			
	K-4								
		on monument in monum n of the original corner	ent box and	accepted	it as a c	areful and fait	hful perpetuation	on	
	•	NW Side Power Pole	AZ 146°	49.86	5'			والعمو	
	Found Nail in	SW Side Power Pole	AZ 146°	50.3	1'	R	A	M	
	Found Nail &	Tag in NE Side P. Pole	AZ 248°	68.9	5'	IN BOX	Wedewe COUNTY 112/94	ld -	
	Found Nail in	N Side Power Pole	AZ 248°	69.3	3'	College.	I flaces	,	
			•		מא מי	5 OTTAWA	COUNTY		
		,			F.M. 0	0150 /7	112/94		
				PEE	R APPR	OVED/2	1.10=1.1		
C.	Description of monume	ent for corner and accessor	ies established	to perpet	uate locati	ng the position o	of the corner:		
	K-4				_				
		on Monument in Monum			•				
		Tag & Nail E Side Powe		AZ.	7°	285.0			
		Tag & Nail NE Side Pow			146°	50.45			
		Tag & Nail SE Side Pow			248°	69.45		. ·	
	O.C. Remon	Tag & Nail SW Side 14"	Oak	AZ.	292°	119.0	15' OF M	ICHIO	

Signed by John P. Clapp -Surveyor's Michigan License No.

LAND SURVEYOR PED LANDE

JOHN P CLAPP

K-4
Recorded in Liber 5, Page 275
August 17, 1987
Cast Iron Monument
Power Pole SE 50.33'
Power Pole SW 69.34'
20" Oak WNW 91.47'
7" Poplar NW 76.47'

WEST # 3000 BRACO # 3000