SURVEY & MEMONUMENTATION

APR 2 4 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filton Day 1077

RECORDED

94 DEC 14 AM 10: 03

Filing Requirement of Act 74, Mich. P.A. 1970 Phylin Carlinan For corners in REGISTER OF DEEDS OTTAWA COUNTY, MI Ottawa_(County) Located In: Corner Code ## M-8 (E1/4 Cor Sec 24) T_5N R_16W 1. Public Land Survey Park Twp. — T _____ R __ 2. Property Controlling in Section 3 Miscellaneous Register of Deeds Stamp & File Number Property in Sec. __ , Recorded Plat _ 5. Private Claims ___ November 28 John P. Clapp , in a field survey on . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Govt Land Office Survey Notes Recorded in Liber 4 Recorded in Liber 6 1832-Surveyor, Calvin Britain Page 185, May 19, 1981 Page 185, Nov 6, 1991 Set 1/2 Mile Post Found 3/4" Iron Pipe from Witnesses Fd Iron in Monument Box Set Cast Iron Monument 10" Hemlock is post Power Pole SW 35.10 (See reverse side for Power Pole Holland Cor 13.91 NW 40.13' additional recordings Power Pole **NNE** 63.18' Power Pole NE 63.10' Liber 6, Page 203) Power Pole ΝE 81.43' Power Pole NW 40.06' 83.23' 18" Oak SE 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-R Found cast iron monument in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner Found Nail & Tag in SE Side Power Pole AZ 36° 63.03' 83.17' Asedoy D. Wedewell P.A. 345 OTTAWA COUNTY Found Nail & Tag in S Side 30" Oak AZ 26° Found P.K. in SE Side Power Pole AZ 321° Found Nail & Tag in NE Side 18" Oak AZ 136° PEER APPROVED 12/12/94 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-8 **Cast Iron Monument in Monument Box** O.C. Remon Tag & Nail NW Side 30" Oak AZ. 26° 83.95' O.C. Remon Tag & Nail NE Side Power Pole AZ. 321° 40.15 O.C. Remon Tag & Nail E Side Power Pole AZ. 191° 121.89

Signed by John P. Clapp

Surveyor's Michigan License No. 1409

O.C. Remon Tag & Nail NE Side 18" Oak

1409

____ Date <u>Dec 2, 1994</u>

FORM APPROVED BY MICHIGAN STATE BOARD OF CALA NORVE O

LAND Surveyor

83.16

REMON LIBER 2 PAGE 136

136°

W:\Docs\SurvRemon.doc

M-8
Recorded in Liber 6, Page 203
March 11, 1992
Cast Iron Monument in Monument Box
Power Pole NW 40.04'
Top Hydrant NE 71.07'
16" Oak SE 83.15'
Holland Cor N 14'