SURVEY & REMONUMENTATION

APR 2 4 1995

For corners in

OTTAWA COUNTY REMONUMENTATION

94 DEC 14 AM 10: 02

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Physical Williams

Ottawa		Located I	n:	Corner Code ##			" orr	AWA CO	UNII Y. I	MI,	
	(County)							ueni	. 1.	x	
1.	Public Land Survey	T 5N	к <u>16</u> W	M-10 (E1/4	Cor Sec 2	25)	4	. 4	, Lt	7'	
.,	,			Park Twp.		,	Å . a :	u eN			
			_		i i	J	W	W			
		Τ	. R			T _r	J-				
2.	Property Controlling	S T	R				V				
	in Section	S T	. R								
3.	Miscellaneous	S T				Register of	Deeds \$	Stamp &	File N	lumber	,
	Property in Sec.	S T	. R		, 				·		
	Lot No,					А В	C D	E F G	HI	JK	L
5.	Private Claims						<u> </u>		_ 1 _ 1		_
						3	_ <u></u>		ĬIJ	Ĩ.	Ĺ
	•					4			10		_[
ı	John P. Clapp	in a field survey or	Nover	nber 30,	19 94	5		Til	Ϊ		Ï
dol	nereby certify that under re										Ţ
	nes 1 and 2 above were i					e ₋lï	Tï		13-1	ï	
	rent manual of survey instr pagement or by a decree of		•	•		, I					Ţ
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3; 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a							20-		-22	23	-2
	irt of Law; established.	re-established, monu	mented, re-monui	mented, recove	red, found as			1			7
	ressed below:			,		10 -30	29	28	-27-	-26 I	2:
NO	TE: Not more than 4 of		ime town and ra	nge, may be r	ecorded	11	- - 	 	\dashv		\dashv
	on this certificate) .				12 31	32	33	—3 '4—	-35	34
	s in the state of			- 1		13					
Α.	, –	Description of original monument and accessories and/or subsequent restoration:									
	M-10										
		fice Survey Notes		Recorded		Page 265					
	-	or, Calvin Britain		Sept. 20, 1993							
	Set 1/2 Mile F		•	•	•	all sides of	interse	ection)			
	12" White Oal		11links	(No Twp. j	og)					•	
	12" White Oal	k S40°W	20 links	NE Corner	· House	SE 11	1.60'				
				SW Corne	r House	NE 10	6.70'				
				SE Corner	Porch Fno		.25'				
				NE Corner			5.23'				
8.	Description of corner	evidence found and/	ог тетпоа арри	ea in restoring	or reestabili	sning comer.					
M-10 Found cast iron monument flush with pavement and accepted it as a careful and faithful pe										.At	
			•	ent and acce	epted it as	a caretul ar	ia raitn	itui per	petua	uon	
	•	n of the orginal co									
		ouse Foundation	AZ 12		1.60	,					
	SW Corner H		AZ 57		6.70'	A				AND ADMINISTRA	7
	SE Corner Po	orch Foundation	AZ 3 ⁴	17° 86	.25'	I d a	AND THE RESERVE	9/1 s			
	NE Corner Ho	ouse	AZ 24	41° 10	5.23'	Merdon		///le	1 July	æ	
		•			P.	A. 345 OT	'AWA"	COUN	ΊY		
						מאטעבט	12	1/2/	94	•	
			•		PEER A	PPROVED.	_/=/	1	/		
C.	Description of monum	ent for corner and a	ccessories estat	olished to perp	etuate locati	ing the position	on of the	e corner	:		
								•			
	M-10										
		Found Cast Iron Monument								-	
O.C. Remon tag & nail in NW Side 2			•		53°		.47'	Ď.	OF	MICE	.
	O.C. Remon tag & nail in W Side 36" (AZ.	153°	47	.21'	PAR.	\~	~~\(\gamma_{\infty} \(\begin{array}{c} \\ \gamma \\ \end{array} \\ \gamma \	1
	O.C. Remon	tag & nail in SE S	ide 15" Oak	AZ.	223°	47	.26'	105	. TOH!	V P. Y	~
		louse Foundation		AZ.	301°	10	8.85'	Hers!	LA	יייה D	12
								1 5	SURV	EYOR	3

Signed by John P. Clapp
Surveyor's Michigan License No.

Date Dec 2, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 GE 103 REVISED JAN., 1983

REMON LIBER 2 PAGE 103

W:\Docs\Surv\Remon.doc