

SURVEY & REMONUMENTATION

NOV 10 1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970
Ottawa County Remonumentation

For corners in
Ottawa
(County)

Located In: Corner Code #

BLENDON TWP?

| | | | | |
|---|-----------|---|------------|-------------------------|
| T | <u>6N</u> | R | <u>14W</u> | K-7, NW Cor-24 |
| T | <u>6N</u> | R | <u>14W</u> | <u>L-7 N 1/2 Cor-24</u> |
| T | _____ | R | _____ | _____ |
| T | _____ | R | _____ | _____ |
| S | _____ | T | _____ | _____ |
| S | _____ | T | _____ | _____ |
| S | _____ | T | _____ | _____ |
| S | _____ | T | _____ | _____ |

RECORDED

1993 SEP 29 PM 3:13

Phyllis Burton
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

1. Public Land Survey

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Randal D. Feenstra a field survey on July 13, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-7 = LCRC#'s L-1, P-409; L-1, P601; L-2, P-191; L-4, P-353; L-5, P-281

L-7 = LCRC#'s L-3, P-26; L-3, P-239; L-5, P-178

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-7
Found Cast Iron Monument
And Witnesses Per
LCRC # L-5, P-281

L-7
Found Cast Iron Monument
And Witnesses Per
L-5, P-178



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-7- Cast Iron Monument per L-5, P-281, Ottawa County, MI, and is accepted as a careful and faithful perpetuation of the position of the original corner.
O.C. Remon. Nail & Tag in P. Pole N28°W 90.88'
O.C. Remon. Nail & Tag in 6" Poplar N70°E 69.25
O.C. Remon. Nail & Tag in 4" Birch S40°E 93.89
O.C. Remon. Nail & Tag in 12" Maple N68°W 91.62 CL Tyler 11' South, CL 56th 0'W.

L-7-Cast Iron Monument per L-5, P-178, Ottawa County, MI, and is accepted as a careful and faithful perpetuation of the position of the original corner.
O.C. Remon. Nail & Tag in P.Pole N30°W 35.09
O.C. Remon. Nail & Tag in 12" Pine S40°W 62.24
O.C. Remon. Nail & Tag in 32" Oak S60°E 121.42
NW cor. of shed foundation S00°E 55.15
CL Tyler - 20' ± South

Signed by Randal D. Feenstra Date July 13, 1993

Surveyor's Michigan License No. 37275