SURVEY & REMONUMENTATION

DFC 0 1 1993

COMMISSION

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 NOV 11 AH 11:55

Delyelis anderin REGISTER OF DEEDS OTTAWA COUNTY, MI

Ottawa Located In: Corner Code ## (County) T 6N R 15W Public Land Survey H-9 T _____ R ____ $(S_1/4 \text{ cor. Sec})$ __ R _ 22. Olive Twp.)

Т

Property Controlling in Section

Miscellaneous Property in Sec.

For corners in

__ R __ _ T ____ R ____ __ R __ __ T __ __ T .____ R ___


... R _

Register of Deeds Stamp & File Number

____, Recorded Plat ____ Lot No. Private Claims ___

I, <u>Douglas J. Koning</u>, in a field survey on <u>September 9</u>, 19 <u>93</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration:

L.C.R.C. L. 1 P. 281 1972	L.C.R.C. L. 5 P. 323 1988
H-9 Found Iron in Mon. Box	H-9 Set C.I.M.
Nail in Face of 12" Oak SW 57.80'	14" Oak SW 58.4'
Nail in face of 18" Oak WSW 152.45'	6" Oak SSE 33.2'
Iron SOUTH 33.34'	P. Pole NE 34.9'

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- H-9 Found Cast Iron Mon. in Mon. Box Centerline 16" Stump Nail W. side 8" Oak 58.21 SW 33.2 SSE 34.97 Nail W. Side P. Pole NF.

This marker is accepted as a careful and faithful perpetuation of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- C.I. Mon in Box (Centerline E-W Road 0.5' North)

Nail and O.C. Remon Tag W. Side 18" Maple Nail and O.C. Remon Tag SE Side 8" Ash
Nail and O.C. Remon Tag W. Side Power Pole
Nail and O.C. Remon Tag SW Side 5" Oak

S3°W 42.03' S51°W 61.77' 34.97' N24°E

S33°E 44.15

of C OF HICKIES

Signed by __ 35995 Surveyor's Michigati License No.

KONING LAND SURVEYOR Date No.

DOUGLAS J.

SEO LAND SUS

10-19-93

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

REMON THOUSE REMON LIBER 1 PAGE 126