

**SURVEY &  
REMONUMENTATION**

DEC 01 1993

**OTTAWA COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

RECORDED

93 NOV 11 AM 11:56

COMMISSION

For corners in

*Richard R. Ballou*  
REGISTER OF DEEDS  
OTTAWA COUNTY, MI

Located In: Ottawa (County) Corner Code #

1. Public Land Survey T 6N R 16W I-11 (NE--Sec 34)  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 Port Sheldon Twp:  
 \_\_\_\_\_  
 \_\_\_\_\_

2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Register of Deeds Stamp & File Number

I, David R. Greer, in a field survey on September 13, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therofore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Recorded in Liber 4 Page 283 Jan. 5, 1982  
 I-11  
 Set Cast Iron Monument  
 Power Pole NW 67.29  
 10" Pine S 63.73  
 7" Cherry SW 52.03  
 St. Sign NE 38.55

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-11  
 Found cast iron monument in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner.  
 Power Pole NW 67.29  
 10" Pine S 63.73  
 7" Cherry SW 52.03  
 St. Sign NE 38.55

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-11  
 Raised C.I.M. in Monument Box with O.C. Remonumentation Iron & Cap  
 AZ= Michigan State Plane Grid Direction  
 O.C. Remon tag & nail in W. side 12" Pine AZ. 190°13' 64.05'  
 O.C. Remon tag & nail in NE Side 8" Tw. Popular AZ. 317°35' 115.21'  
 O.C. Remon tag & nail in NW Side 10" Maple AZ. 53°38' 94.81  
 O.C. Remon tag & nail in N. Side 6" Cherry AZ. 106°08' 148.03



Signed by David R Greer Date SEPT. 13, 1993

Surveyor's Michigan License No. 16042