

SURVEY & REMONUMENTATION

APR 25 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC -8 PM 12:31

D. J. ...
REGISTER OF DEEDS
OTTAWA COUNTY, MI

For corners in

<u>Ottawa</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>6N</u> R <u>16W</u>	<u>L-7 (N1/4 Cor. Sec. 24)</u>
	T _____ R _____	<u>Port Sheldon Twp.</u>
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

John P. Clapp, in a field survey on November 15, 19 94, to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-7 Govt Land Office Survey Notes May 1832, Surveyor Calvin Britain Post 15" Beech S30°E 17 links 3" Beech N46°E 18 links Note: See reverse side for additional recordings	L-7 Recorded in Liber 1 Page 39, June 29, 1971 Iron Pipe 6" Spruce NW 35.70' 6" Spruce NE 29.87' 10" Ash SE 38.02'	L-7 Recorded in Liber 1 Page 115, Oct. 29, 1980 1/2" Steel Rod 7" Spruce NW 52.85' 6" Pine NE 29.41' 8" Red Pine N 52.62' "T" Iron N 33.01' 5" Red Pine S 67.03'
---	--	--

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-7
Found cast iron monument and accepted it as a careful and faithful perpetuation of the position of the original corner

All ties gone

RA. 345 OTTAWA COUNTY
PEER APPROVED 11/21/94
Harvey D. Newell

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-7 Found Ottawa County Cast Iron Monument O.C. Remon tag & nail in W Side 8" Pine	AZ. 05° 37.13'
O.C. Remon tag & nail in W Side 8" Maple	AZ. 187° 62.59'
O.C. Remon tag & nail in N Side 6" Sassafras	AZ. 118° 65.53'
"X" Top of W End 14" Concrete Culvert	AZ. 314° 34.24'



Signed by John P. Clapp Date November 16, 1994
Surveyor's Michigan License No. 14091

077 AUAH

L-7

Recorded in Liber 4, Page 206
June 25, 1981

Set Cast Iron Monument

6" Pine	S	67.05'
8" Pine	NW	52.87'
8" Pine	NE	29.43'
CL Road	S	8.50'

L-7

Recorded in Liber 5, Page 368
June 23, 1989

ReSet Cast Iron Monument

6" Pine	S	67.05'
8" Pine	NW	52.87'
8" Pine	NE	29.43'
Iron Bar	S	33.00'

RECORDED
INDEXED
SERIALIZED
JUN 23 1989
FBI - MEMPHIS

RECORDED
INDEXED
SERIALIZED
JUN 23 1989
FBI - MEMPHIS