

**SURVEY & REMONUMENTATION**

DEC 01 1993

**OTTAWA COUNTY REMONUMENTATION**

**LAND CORNER RECORDATION CERTIFICATE**

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 NOV 11 AM 11:56

*Deborah K. Calloway*  
REGISTER OF DEEDS  
OTTAWA COUNTY, MI

COMMISSION IN  
For corners in

Ottawa (County) Located In: Corner Code #

1. Public Land Survey T 6N R 16W L-9 (N 1/4-Sec 25)  
 T \_\_\_\_\_ R \_\_\_\_\_ Port Sheldon-Twp.  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 In Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Register of Deeds Stamp & File Number

I, David R. Greer, in a field survey on September 13, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Recorded in Liber 5  
 Page 98, Dec. 20, 1983  
 L-9  
 Set cast iron monument  
 Fence Post SE 65.70  
 10" Pine NE 47.57  
 8" Pine NW 57.70  
 5" pine SSW 47.90

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-9  
 Found cast iron monument in monument box and accepted it as a careful and faithful perpetuation of the position of the original corner  
 Fence Post SE 65.70  
 8" Pine NW 57.70  
 5" Pine SSW 47.90

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9  
 C.I.M. in Monument Box  
 AZ- Michigan State Plane Grid Direction  
 OC Remon tag & nail in W side P. Pole AZ. 18°36 75.99'  
 OC Remon tag & nail in W side 8" Pine AZ. 336°27 44.56'  
 OC Remon tag & nail in W side P. Pole AZ. 172°33 234.08'  
 OC Remon tag & nail in NW side 8" Pine AZ. 39°00 59.88'



Signed by David R. Greer Date SEPT. 13, 1993

Surveyor's Michigan License No. 16042