

SURVEY & DOCUMENTATION

APR 05 1996

Ottawa County Remonumentation
LAND CORNER RECORDATION CERTIFICATE

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

95 DEC 12 PM 1:50

D. J. Rosema
REGISTER OF DEEDS
OTTAWA COUNTY, MI

For corners in

Ottawa (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>T7N</u> R <u>R14W</u>	H-3
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Maurice J. Rosema, in a field survey on March 30, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3								●					
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-3
GLO - 1837 by John Mullett D.S. Section cor. not set, falls in River
L.C.R.C. recorded in Liber 3, Page 350 - June 28, 1979
On Steel manhole cover
Steel Co. sign post
Bottom LH cor. on nameplate of old swimming rock NE 34.3'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-3
Found X cut in concrete on bridge deck
All other wit. are gone but this location checks with data from the files of Nederveld Assoc. and Tru-Line Surveying P.C.

P.A. 345 OTTAWA COUNTY

PEER APPROVED 12/11/95

Nederveld
RDY

I hereby accept this corner as a correct and accurate perpetuation of the position of the section corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-3
X cut in concrete bridge deck
N-S expansion joint (also centerline of conc. road) S90°E 10.05'
West edge of vertical conc. (W edge of bridge deck) N90°W 9.28'
E-W expansion joint S0°E 4.62'
N'ly E-W expansion joint N0°W 76.12'



Signed by *Maurice J. Rosema*
Surveyor's Michigan License No. 27459

Date October 21, 1995