SURVEYS TIT YONUMENTATION

_ , Recorded Plat _

Ottawa County Remonumentation

RECORDED

95 DEC 12 PH 4: 52

APR 0.5 1996 LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 COMMISSION

• •, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Physicis Carion
ode#	REGISTER OF DEEDS OTTAWA COUNTY, HI

Ottawa (County)	Located In:	Corner Code ##	REGISTER OF DEEDS OTTAWA COUNTY, HI
1. Public Land Survey	T T7N R R14W	H-5	
,	T R		
Property Controlling in Section	S T R S T R		
3. Miscellaneous Property in Sec.	STR STR		Register of Deeds Stamp & File Number
rioperty in Sec.	· · · ·		

in a field survey on Dec. 28 94 Maurice J. Rosema do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO - 1832 by Noah Brookfield

for Calvin Britain D.S. Set post

For corners in

4. Lot No.

5. Private Claims _

20" Beech S 24 1ks.

10" Hemlock N3°E 45 lks.

L.C.R.C. recorded in Liber 4, Page 277 - Dec. 31, 1981

Steel bar

X cut in E end conc. culv. NE 69.55'

X cut in S end conc. culv. SE 53.75'

Street sign

Power pole

c/l asphalt

10

WNW 22.43

NW 167.72'

E 0.3'

X cut in S end conc SE 53.78' culv.

X cut in E end conc

NE 69.55

L.C.R.C. recorded

in Liber 5,

Aug. 1, 1985 3/4" steel bar

Page 224 --

culv.

c/l st sign SE 51.30

At c/1 X of roads

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: c/l st sign WNW 22.41 Found C.I. mon. in mon. box On centerline of N-S bit. conc. road and on centerline of bit. conc. road to E

> P.A. 345 OTTAWA COUNTY PEER APPROVED

I hereby accept this corner as a correct and accurate perpetuation of the position of the original corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-5

H-5

C.I. mon. in mon. box

Set nail and O.C. tag in S side wood sign post

Set nail and O.C. tag in W side P pole

Set nail and O.C. tag in S side 3" Maple

Set nail and O.C. tag in W side P pole Found X cut in top of culvert

Found X cut in top of culvert

N11°W 167.96' S87°W 59.02' S15°W 253.08' N61°E 59.82'

N63°E 74.26'

S59°E 57.07'

MAURICE J. ROSEMA LAND SURVEYOR NO. 27459 PROFESSION

Surveyor's Michigan License N

/______Date __November 20, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 15

REVISED JAN., 15