DEC 1 6 1996

COMMISSION

## OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74,	
Ottawa Located In: Corner Code #	RECORDED
(County) Robinson Twp  1. Public Land Survey T <u>7N R 15W G-8 W4 corner T R Section 22</u>	98 HOV 14 AH 11: 29
T	REGISTER OF DEEDS OTTAWA COUNTY, MI  Register of Deeds Stamp & File Number
4. Lot No	2 above were in structions of the
United States Department of the Interior, Bureau of Land Management or by a decree of a Couthat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules Board of Land Surveyors or by a Decree of a Court of Law; established, re-established recovered, found as expressed below:	s of the Michigan _
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25 11 31 32 33 34 35 36
A Description of original monument and accessories and/or subsequent restorated a 1/4 corner common to Sections 21 and G.L.O. May, 1832 Calvin Britain Set 1/2 mile post 7" Pine N67°E 86 links 10" Tamarack N15°W 65 links	
B. Description of corner evidence found and/or method applied in restoring or re	eestablishing corner:
G-8 1/4 corner common to Sections 21 & 22 Found R.R. Spike in Mon. Box Found P.P. N40°W 99.30' Found St. Sign 27.5'	PA. 345 OTTAWA COUNTY PEER APPROVED 9-16-96  J.D. 71.
Accepted as a careful and faithful perp position of the corner.	etuation of the original
G-8 1/4 corner common to Sections 21 and Replaced R.R. Spike with 3/4"x2' Iron be 0.C. Remon tag & nail in N.W. side 10" 0.C. Remon tag & nail in S. side 5" Che 0.C. Remon tag & nail in S. side P.P. 0.C. Remon tag & nail in N.E. side P.P. Corner on 4 Road N., S. & W. and on occ	par with OC Remon Cap in Mon. Box Poplar N40°W 75.07' Erry S70°E 51.23' N63°W 66.32' N36°W 99.46' Eupation line East  CALP ENGLERIJE PROFESSIONAL SURVEYOR NA
Signed by Carl P. Englest fr. Surveyor's Michigan License No. 18987	Date Sept. 11, 1996 ONAL SUFF