Ottawa County Remonumentation

RFCORDED

CAMESSION LAND CORNER RECORDATION CERTIFICATE 93 DEC 15 AM 9: 29

| Ear | COMPARE | in | |
|-----|---------|----|--|

Filing Requirement of Act 74, Mich. P.A. 1970

| (W) 6 | policie | 9.0 | Breezeway) |
|-----------------------|-----------|---------|------------|
| م به وسد اربيون. م | Judicinet | 100 m | men n |
| 11 | REGISTE | r of u | ££U5 |
| v | OF TABLE | COLLIN' | (V MI |

<u>Ottawa</u> Located In: Corner Code ## DITAWA COUNTY, MI Robinson Township T 7N R 15W G - 111. Public Land Survey T _____ R ____ NW corner T _____ R ____ Section 34 T _____ R _ __ T <u>.___</u> R ____ 2. Property Controlling in Section S ____ T ___ R ___ S ___ T ___ R __ S ___ T ___ R __ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. ____ , Recorded Plat _____

5. Private Claims __ Carl P. Englert Jr. , in a field survey on July 8 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 12

on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L.C.R.C. Liber2, Page 415, (11-30-73) Found 1" iron bar

NE 53.50 12" Pine NE 61.42 P.P. SE 46.56 St. sign

L.C.R.C. Liber 6, Page 58, (10-12-9

Found 1" iron bar, set C.I.M.

6" Maple SW 42.90'

P.P. NE 61.46' P.P. SE 57.02'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 4" Harrison Monument in monument box and accepted as a careful and faithful perpetuation of the position of the original corner.

6" Maple SW 42.90'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11 Set O.C. Remon. Cap over Harrison C.I.M. in Mon. box

O.C. Remon Tag & Nail in NW side P.P. N40 degrees E 63.07'

O.C. Remon Tag & Nail in N side 15" Pine N 75 degrees E 86.59'

O.C. Remon Tag & Nail in SE side 6" Maple S 40 degrees W 42.93'
O.C. Remon Tag & Nail in SW side P.P. S 45 degrees E 57.29'
O.C. Remon Tag & Nail in NE side 9" Oak N 44 degrees W 81.13'

Signed by Caul P. Englect A. Date December

18987

FORM APPROVED BY MI Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SORVEYOR !!

GLERT JR.