SURVEY & REMONUMENTATION

APR 2 4 1995

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

RECORDED

94 DEC 15 AM 11:51

-	corners GONMISSION	
-or	comers m """	

Filing Requirement of Act 74, Mich. P.A. 1970

Dolydie alleman

Ottawa (County)		Located In: Robinson Twp.	Corner Code ##		REGISTER OF DEEDS OTTAWA COUNTY, MI			
1.	Public Land Survey	T <u>7N</u> R <u>15W</u> T R T R T R	M-8 E. 1/4 Corne Section 24	r				
2.	Property Controlling S	T R						
_		T R						
3.		T R T R		Register of Deeds Stamp & File Number				
4.	Lot No, Recorde	d Plat		A B	C D E F G	ні	JKLM	
5.	Private Claims			2		ŢŢ		
				3				
				4 _ 7_		10		
į Ca	arl P. Englert, in a fi	eld survey on Decembe	e <u>r 05</u> , 19 <u>9</u>	14 , 5		<u> </u>		
do h	nereby certify that under requiremen	its of P.A. 74, Michigan P.A. of	1970, the corner points me	entioned 6 1	17 16	15	1413	
in li	nes 1 and 2 above were in conformation of survey instructions of	mance with regulations and a of the United States Departme	rules theretore as require ent of the Interior. Bureau	of Land				
Маг	nagement or by a decree of a Court o	f Law and/or that the corner p	oints mentioned in lines 3	,4 and 5 8 19	20 21	22	23 24 4	
	we were in conformance with the rul				 	1-1-		
	irt of Law; established, re-establ ressed below:	isnea, monumentea, re-mo	numentea, recoverea, it	1030	29 28	-27	 26 -25	
•	TE: Not more than 4 corners,	all in the same town and	range, may be record	ed 11	 		 	
	on this certificate.			1231	32 33	34	3536	
_				13	 		1 1 1	
A.	Description of original monumer M-8 East 1/4 corne		or subsequent restorat	ion:				
	Original Gov't cor		332 LCRC I	iber 5, Page	373 (6/2)	1/89)	
	by Calvin Britair		M-8	g	(1, 1		,	
	-		Set CI					
	Set 1/2 Mile Post	·		ner of 19-7-			52.65	
	Hemlock 10" S46°W	*		n E face 18"			37.89	
	Hemlock 16" N 40W	15 Links		n S face 10" n SE face 16			22.24 25.76	
		•		n W face 40"			32.24	
_	(See Back of Page)				* 11 m2=		,	
В.	M-8 East 1/4 corne		piled in restoring or re-	езгаризнину финаг.				
	Found 4" Harrison	CIM 2" above gr	cound					
	Found Nail in E. f	ace 18" Birch	SSE	37.89'				
	Found Nail in S. 1	Tace 10" Birch	WEST					
	Found 16" Oak	_	NORTH	26.00'+/-				
	Found 40" Twin Oal	•	NE	32.00'+/-				
	Accepted as a care		ul perpetuatio	on of the		•		
	original position	of the corner.		P.A. 345 OTTAW	A COUNTY			
			PEER	APPROVED/	2/12/44		- 11	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

M-8 East 1/4 corner Section 24

4" Harrison Cast Iron Monument

O.C. Remon. Tag & Nail in W. side 40" Twin Oak
O.C. Remon. Tag & Nail in E. side 20" Yel. Birch
O.C. Remon. Tag & Nail in S.W. side 24" Oak
O.C. Remon. Tag & Nail in S. side 12" W. Birch N200W 30.85' S12°E 37.931 N400W 36.71

WEST 22.05'

Signed by Carl P. Englant Surveyor's Michigan License No. 18987

OF MICHIE CARL P. ENGLERT JR. **PROFESSIONAL** SURVEYOR No. 18987

WALE BY THE TANK TON

LCRC Liber 6, Page 41 (8/7/81)
M-8= Set 1" Pipe with cap midway and on line
North 14" Oak 25.94'
N.N.E. 34" Oak 32.00'
S.S.E. 18" Birch 38.28'
Allendale Corner South 52.15'