

1992

RECORDED

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE

93 DEC 16 PM 1:00

Filing Requirement of Act 74, Mich. P.A. 1970

Phyllis R. Latham
REGISTER OF DEEDS
OTTAWA COUNTY, MI

For corners in

Ottawa (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>7N</u> R <u>16W</u>	H-7 S $\frac{1}{2}$ Corner Section 15 Grand Haven Twp
	T _____ R _____	
	T _____ R _____	
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	<i>Sec. # 1 pm</i>
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, THOMAS E. JOINER in a field survey on 11-3-1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- Set Cast Iron Monument
Inscribed "Section Corner"
Liber 4, Pg. 71 6-5-80
- Iron Pipe
Liber 3, Pg. 39 3-10-76
- 15" Oak N. 31.51
- 12" Spruce NE. 36.95
- 20" Oak SE. 29.93
- RR Sign SW. 25.95
- 16" Oak N 31.51
- 12" Spruce NE 36.95
- 20" Oak SE 29.93

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found cast iron monument and accepted as a careful and faithful perpetuation of the position of the original corner.

- 15" Oak N. 31.51
- 12" Spruce N.E. 36.95
- 20" Oak S.E. 29.93



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Cast Iron Monument
- O.C. Remon tag & nail in East side 9" Oak S. 03° E. 62.72
- O.C. Remon tag & nail in South side 14" Cherry N. 55° W. 65.49
- O.C. Remon tag & nail in West side 20" Oak N. 03° W. 31.00
- O.C. Remon tag & nail in North side 8" Spruce S. 48° E. 57.39

Signed by Thomas E. Joiner Date 11-19-93
 Surveyor's Michigan License No. 18435