

COMMISSION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 DEC 16 PM 1:00

For corners in

Richard Redman
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Ottawa (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>7N</u> R <u>16W</u>	<u>I-6 E¹ corner</u>
	T _____ R _____	<u>Section 15</u>
	T _____ R _____	<u>Grand Haven Twp</u>
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, THOMAS E. JOINER in a field survey on 11-3-, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Found 2" Pipe
Liber 2, Pg. 639-640 10-9-74

Set Cast Iron Monument Inscribed
"Section Corner" Liber 4, Pg. 67 6-5-80

S.W. 52.74 15" Oak
S.E. 51.60 30" Oak
N.E. 77.33 24" Oak

15" Oak S.W. 52.74
30" Oak S.E. 51.60
24" Oak N.E. 76.81
C_L St. Sign E. 21.40

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found cast iron monument and accepted it as careful and faithful perpetuation of the original corner.

15" Oak S.W. 52.74
30" Oak S.E. 51.61
24" Oak N.E. 76.81



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Cast Iron Monument

O.C. Remon tag & nail in East side	15" Oak	Bearing S.	26° W.	53.30
O.C. Remon tag & nail in West side	5" White Pine	N.	82° E.	39.23
O.C. Remon tag & nail in West side	13" Oak	Bearing N.	31° W.	109.39
O.C. Remon tag & nail in East side	13" Oak	Bearing S.	68° W.	84.10

Signed by Thomas E. Joiner
Surveyor's Michigan License No. 18435

Date 11-19-93