

CONVEY &
REMONUMENTATION

APR 24 1995

COMMISSION OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 14 AM 9:42

D. J. Robinson
REGISTER OF DEEDS
OTTAWA COUNTY, MI

or corners in

OTTAWA <small>(County)</small>	Located In:	Corner Code #
Public Land Survey	T <u>7N</u> R <u>16W</u>	K-6, W $\frac{1}{2}$ Corner
	T _____ R _____	Section 13
	T _____ R _____	Grand Haven Twp.
	T _____ R _____	
Property Controlling	S _____ T _____ R _____	
in Section	S _____ T _____ R _____	
Miscellaneous	S _____ T _____ R _____	
Property in Sec.	S _____ T _____ R _____	

Register of Deeds Stamp & File Number

Lot No. _____, Recorded Plat _____
Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2							
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

THOMAS E. JOINER in a field survey on 10-28-94, 19 94,
I hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

Description of original monument and accessories and/or subsequent restoration:		
05-17-1832	Liber 4, Pg. 67, 06-05-80	Liber 2, Pg. 649, 10-09-74
Post set by Calvin Britain, D.S. Set cast iron monument		Found 5/8" rod
N 31°W 14 12" Brown Ash	NW 37.39 Twin Maple	NW 37.39 Twin Maple
S 65°E 9 6" Brown Ash	SW 43.04 10" Oak	SW 43.04 10" Oak
	E. 45.91 12" Maple	E. 45.91 12" Maple
	SE 70.49 Twin 7" Maple	

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Cast Iron Monument and accepted as a careful and faithful perpetuation of the position
of the original corner.

Liber 4, Pg. 67, 06-05-80	Liber 2, Pg. 649, 10-09-74
NW 37.39 Twin Maple	NW 37.39 Twin Maple
SW 43.04 10" Oak	SW 43.04 10" Oak
East 45.91 12" Maple	East 45.91 12" Maple
SE 70.49 Twin 7" Maple	

P.A. 345 OTTAWA COUNTY
PEER APPROVED 12/12/94

Madison P. Newell



Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Cast Iron Monument

O.C. Remon. Tag & Nail in N side 22" Maple	Az. 80°	46.10
O.C. Remon. Tag & Nail in SW side Twin 9" Maple	Az. 140°	71.18
O.C. Remon. Tag & Nail in E side 33" Maple	Az. 245°	99.41
O.C. Remon. Tag & Nail in S side 17" Oak	Az. 345°	43.30

Signed by Thomas E. Joiner Date 11-28-94
Surveyor's Michigan License No. 18435