SURVEY & REMONUMENTATION

APR 2 4 1995

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AM 11: 47

Polythis Calleran

_	Ottawa (County)	Located In:	Corner Code -++	REGISTER OF DEEDS OTTAWA COUNTY MI
1.	Public Land Survey	т <u>8N</u> R <u>13W</u> т R	<u>E-12 (W%, 33)</u> Wright Twp.	
		T R		
	•	T R		
2.	Property Controlling	S T R		
	in Section	S T R		
	Miscellaneous	S T R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		
4.	Lot No.	, Recorded Plat		

, ₁₉ <u>9</u>4 November 25, Donald W. Schiele, in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

E-12 % corner common to Sections 32 & 33, Wright Twp. L.C.R.C. recorded in Liber 3, Page 46, 3-29-76
Set cast iron Mon.
Triple 16" poplar SE 133.77 <u>Original</u> Government

Corner Record:

Set qr sec post

5. Private Claims _

between Sec. 32 & 33

Post

Sugar 12

N67W 31 S17E 23 q Beech

Enoch Hammele, Deputy Surveyor

Between 9-18 and 9-26, 1838

P. pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-12 Found Cast Iron Monument inscribed "Section Corner", 1½" below surface, and accepted as a careful and faithful perpetuation of the position of the original corner.

SW corner, brick face to House # 14846 Found PK nail in South side of Power Pole

N23°17'E N71°30'E

ENE

250.75'(E)

133.77'

148.52'

148.47'(E)

Found nail in South side of Power Pole

N71°30'E

148.37'(E)

P.A. 345 OTTAWA COUNTY

PEER APPROVED_ 12/12/90

OF MICHIG Donald W Schiele Land Surveyo

L.C.R.C. recorded in Liber 6,

Page 26, 1-3-90 Found Iron PK in S side PP N71°36'E 146.55'

N23°17'E 250.70'

SW cor Br. Hse

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-12 Cast Iron Monument inscribed "Section Corner", 11/2" below surface.

N23°17'E N71°30'E 250.75'(E)

S25°E

148.39'(E)

SW corner, brick face to House # 14846 Set Ottawa County Remon Tag & nail in South side of Power Pole Set Ottawa County Remon Tag & nail in West side of Power Pole

S20°W

361.86'(E) 361.83'(E)

Set Ottawa County Remon Tag & nail in East side of Power Pole Centerline asphalt road North & South, 0.4' West

Field line to West, 33'± South

w. Ilile

Surveyor's Michigan License No. _

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, REVISED MAY 14, 197 REVISED JAN., 198