APR 0 5 1996

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

1970

For corners in	COMMISSION	Filing Requ	irement of Act 74, Mich.	P.A.
Ottawa	Loc	ated In:	Corner Code ##]
(County			0011101 0000	

RECORDED

95 NOV 15 PH 21 07

Pdy die Rullman REGISTER OF DEEDS OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

Ottaw Polkton Twp. T 8 N R 14 W A - 3Public Land Survey NW Corner T _____ R ____ Section 7 ____ R _ T _____ R _ Common corner 2. Property Controlling __T ____R _ \$ ____ T ____ R __ w/M-3, in Section Crockery S ____ T ___ R ___ Miscellaneous __ T _____ R __ Property in Sec.

_ , Recorded Plat _ 5. Private Claims _

I, Carl P. Englert, Jr. , in a field survey on October 9 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 12
- A. Description of original monument and accessories and/or subsequent restoration:
 - Corner common to Sections 6 & 7, T 8 N, R 14 W & Sections 1 & 12, T 8 N, R 15 W. (LCRC Liber 2, Page 253 8/3/1973 Original corner set March 1837

By John Mullett D.S.

Set Corner of Sections 1 & 12.

Hemlock 18" S 32° W 55 Links

Hemlock 24" N 26° W 34 Links same (

(LCRC Liber 2, Page 453 11/29/1973

10 11

Set 5/8" Rod from ties SW 43.3' St. Sign

SE 39.5 ' F. Post

NE 53.15' 18" Spruce

see other side

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Corner common to Sections 6 & 7, T 8 N, R 14 W & Sections 1 & 12, T 8 N, R 15 W. Found 4" CIM in center of intersection of Gravel Roads 4" deep

Found Fence Post SE 41.98' (Post is Leaning)

Found Stop Sign SW 43.4'± (Leaning)

Found 26" Spruce NE 53.30'

Found Telephone Pedestal NW 40.60'

Accepted as careful and faithful perpetuation of the position of the original corner.

P.A. 345 OTTAWA COUNTY

C. Description of monument for corner and accessories established to perpetuate localing the position of monument for corner and accessories established to perpetuate localing the position of monument for corner and accessories established to perpetuate localing the position of monument for corner and accessories established to perpetuate localing the position of monument for corner and accessories established to perpetuate localing the position of monument for corner and accessories established to perpetuate localing the position of the perpetuate localing the perpetuate loc

A - 3 Corner common to Sections 6 & 7, T 8 N, R 14 W & Sections 1 & 12, T 8 N, R 15 W. 4" CIM

Ottawa County Remonumentation tag and nail in W. Side 26" Spruce N 390 E 53.03'

Ottawa County Remonumentation tag and nail in E. Side P.P. S 150 W 119.95'

Ottawa County Remonumentation tag and nail in E. Side P.P. N $10^{\rm O}$ W 185.52'

Ottawa County Remonumentation tag and nail in S. Side P.P. N 78° E 246 A8 DE PATE CAPI B

Cail P. Englat Surveyor's Michigan License No.

_ Date _ 10/17/

ENGLERT JR PROFESSIONAL SURVEYOR

REVISED MAY 14, 1975

REVISED JAN., 1983

A - 3 M - 3

Polkton Twp. T 8 N, R 14 W
Crockery Twp. T 8 N, R 15 W
LCRC Liber 4, Page 96 August 12, 1980.
Found 5/8" Iron Bar, Set CIM
St. Sign 43.4'
Fence Post SE 41.98'
18" Spruce NE 53.30'
Center of Telephone Pedestal NW 40.60'

\$ 11.00 CORNE