SURVEY & REMONUMENTATION

APR 2 4 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AMII: 47

For corners in

John Mullett, Deputy Surveyor

	Ottawa	Located In:	Corner Code ##		
	(County)				
1.	Public Land Survey	T 8N R 14W	K-12 (W%, 36) Polkton Twp.		
		T R	POINCOR TWP.		
		T R			
		T R			
2.	Property Controlling	S T R			
	in Section	S T R			
3.	Miscellaneous	S T R			
	Property in Sec.	S T R			

Deleveris Rademan REGISTER OF DEEDS OTTAWA COUNTY.MI

	R	Register	of Deeds	Stamp &	k File I	Numbe	er .
4. Lot No, Recorded Plat _ 5. Private Claims			B C D	E F	<u>я</u> н і	ı j k	;
	•	3	1 1		3	2	
, Donald W. Schiele, in a field surv	ey on December 3, 19 94	, 5	· }		10	_11_	-12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				16	15	14	-13
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as			19 20	21—	22-	_23	24
NOTE: Not more than 4 corners, all in the on this certificate.	ne same town and range, may be recorded	10	30 29	2B 	—27— —34—	—26— —35—4	—25 —36
K-12 % corner common to Secti		13 -					II
Corner Record:	L.C.R.C. recorded in Liber 2, Page 815, 9-11-75		Liber	.C. re 4, Pa			ì
Set qr section post between Sec. 35 & 36	Iron PK nail in first fence post		4-1-8 Set C	2 ast Ir	on Mo	onume	∍nt
Post Beech 14 N 5E 15	South of corner S PK nail in corner fence post W	16.42'		sh Post	NE W	122. 0.	197. 160.
Do 6 S18W 05	PK nail in first fence post			Post			.13'

April 8, 1837

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
K-12 Found Cast Iron Monument inscribed "Section Corner", 3" below surface, and accepted as a careful and faithful perpetuation of the position of the original corner.

North of corner

we a careran and rangering perpendicular and percentage			
Found nail in West side of 17" Ash	N75°E	122.791	
Found nail & cap in East side of 6" X 6" Fence Post	South	8.47	
Found PK nail in East side of 6" X 6" corner Fence Post	West	0.291	
Found nail & cap in East side of 6" X 6" corner Fence Post	West	0.20 ¹ 8.09 ¹	A.
Found nail & cap in East side of 6" X 6" Fence Post	North	8.091	<i>a</i> .
·			₽ 7

OF MICHIG PLE OF MICH Donald W. Schiele Land Surveyo No. MAPPO LAND

8.441

C. Description of monument for corner and accessories established to perpetuate locating the pos	sition of the con	ner: "*********				
K-12 Cast Iron Monument inscribed "Section Corner", 3" below surface.						
Set Ottawa County Remon Tag & nail in West side of 18" Ash	N10°E	168.321				
Set Ottawa County Remon Tag & nail in South side of 14" Ash	N78°30'E	120.32'				
Set Ottawa County Remon Tag & nail in East side of 6" X 6" Fence Post	South	8,441				
Set Ottawa County Remon Tag & nail in South side of 20" Ash	N89°W	57.72				
	1105 11	0, 1. =				
On fence lines North, South & West						

P.A. 345 OTTAWA COUNTY

Fence Post

5.74

23517

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983