OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

RECORDED 91: DEC 15 ANTI: 52

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			John Merchanter
Ottawa (County)	Located in: Crockery Twp.	Corner Code ##	SURVEY & COUNTY, MI
4 Dublin Land Currou	T <u>8N</u> R <u>15</u> W	G-11	REMONUMENTATION
Public Land Survey	T R	NE Corner	
	T R	Section 33)EC ⊎ 5 2000
	T R		JEO & COOO
2. Property Controlling	S T R		
in Section	S T R		SECTION
3. Miscellaneous	S T R		· ·
Property in Sec.	S T R		Register of Deeds Stamp & File Number
rioperty in Oco.			
4 Lot No. B	ecorded Plat		
	ocoraca riat		A B C D E F G H I J K L M
5. Frivate Olainis			2 6 5 4 3 4 2
			3
			4 7 7 8 9 10 10 11 12
Idari B Englart	, in a field survey on May 27	1 19 5	
do hereby certify that under red	uirements of P.A. 74, Michigan P.A. o	1970, the corner points m	entioned [
in lines 1 and 2 above were in	conformance with regulations and	rules therefore as require	ed in the
current manual of survey instru	actions of the United States Departm	ent of the Interior, Bureau	of Land 7
Management or by a decree of a	Court of Law and/or that the corner	points mentioned in lines 3	4 and 5 8 19 20 21 22 23 24
above were in conformance wit	h the rules of the Michigan Board of e-established, monumented, re-mo	Land Surveyors or by a De Soumented recovered for	ound as
expressed below:	E-established, monumented, to me	mamonitos, rodovorda, r	10 30 29 28 27 26 25
	orners, all in the same town and	range may be record	ed 11
on this certificate.	Allers, an in the same tour and	runge, may be record	12 1 12 13 13 13 13
on this certificate.			13
A. Description of original	monument and accessories and/	or subsequent restorat	
G-11 corner co	ommon to Sections 2	7,28,33 & 34	
Original gov'	t corner set March,	1837 LO	CRC Liber 4, Page 28 (1/24/80)
by John Mulle		Se	et Cast Iron Monument Inscribed
27 001111 1111111		" 5	Section Corner"
Set Post			ew Ties Taken:
Pine 10" S40°	E 22 Links	Set Tie N	Wail in Side P.P. East 34.58'
Pine 24" N290	# 83 Links	Set Tie 1	Vail in Sd. of Tw. 28"Ch. Elm S3.2
		g Flag Po	ole West 79.67'
		NE Cor. I	House Foundation SW 59.30'
(See back of]	ρage)	€ Drivewa	ay North 15.5'+/-
B. Description of corner e	vidence found and/or method ap	oplied in restoring or re	establishing corner:
G-11 corner con	mmon to Sections 27	,28,33 & 34	
	son Cast Iron Mon.	6" Deep	1 1 1 1 7 7 F
Found P.P. Eas	t 34.58'		P.A. 345 OTTAWA COUNTY
Found Tw. 28"	Chinese Elm South 3	.25'	12/12/94
Found Flag Pol	e West 79.67'		PA. 345 OTTAWA COUNTY
Found NE corne	r Hse. foundation 5	9.30	
		1 normotuatio	n of the original
Accepted as a	careful and faithfu	r berberggero	or one originar
position of th	e Corner.		
	•		
C. Description of monume	ent for corner and accessories e	stablished to perpetuat	e locating the position of the corner:
	mmon to Sections 27		
G-11 COLUET CO	minor of occorone 27	,,	
4" Harrison Ca	st Tron Mon-		
U G Demon wa	g & Nail in W. side	30" Tw. Elm	SOUTH 3.23'
O.C. Remon. Ta	g & Nail in W. side	10" Maple	N12°E 117.02'
O.C. Remon Ta	g & Nail in N. side	P.P.	EAST 34.59'
C Flagpole	A Or HOTT THE M. STORE		WEST 79.67'
NE Corner Hse.	Foundation		S650w 59.12
WE Corner use.	10011001011		THE PARTY OF THE P
			S650W 59.12
			CARL P. C.
_ ^	1		夏の/ ENGLERT JR. \乙島

PROFESSIONAL SURVEYOR

SIONALE ON A DESCRIPTION OF THE PROPERTY OF THE PROPER

REMON LIBER 2 PAGE 330

Surveyor's Michigan License No. _