## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	1 11/2 1
1. PUBLIC LAND SURVEY_	_ т. <u>8</u> , R. <u>/6</u> .	H-2	O Carlo
2. PROPERTY CONTROLL- 6 ING IN SECTION		<i>A</i> -2	Not his
3. MISCELLANEOUS PROPERTY IN SECTION	,T		
4. LOT NO , REC	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 1962, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on Sept. 1962, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original mo	nument and accessories and/	or subsequent restoration:	
0 1			
Sugar 14"	N.71° E. 20 link. S. 63°W. 7 link.	r's	
Beach 4"	S. 63 W. 7 link.	\$	
B. Description of corner evid Hy I Ron Rod MM. Buck Inn.			Survey in Into 1750
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  34 Ieon Rod			
N 45°W N. 65 W.	12" Maple S 34" Maple S 18" Maple ( 12" Elm (Lean	tump 12' Long)	
S. 15 E.	18" Maple	Stump 15' Long	
S. 84 E.	12" Elm Cenn	nris Enst)	
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN RE			(SEAL)
FOR STATE AND UNITED S	TATES AGENCIES:	-	
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR (SEAL)			
			( SEAL !