

SURVEY & REMONUMENTATION

APR 05 1996

COMMISSION

**OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Ottawa (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>8N</u> R <u>16W</u>	J-7, S $\frac{1}{2}$ corner
	T _____ R _____	Section 14
	T _____ R _____	Spring Lake Twp
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	

RECORDED

95 NOV 29 PM 1:34

Daphne Williams
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	13	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Thomas E. Joiner, in a field survey on 11-9-95, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

03-29-1837	Liber 1, Page 491 07-06-72
Post Set By J. Mullett	5/8 Rod Set From Bearing and Distance on Recorded Plat
N 39°E 13 30" Oak	NNW 47.09 24" Oak
S 16°W 11 10" Pine	WSW 39.97 Twin Catalpa
	NE 4.35 17" Oak

P.A. 345 OTTAWA COUNTY
PEER APPROVED 11/20/95

Kendall D. Hedewick
1207

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Cast Iron Monument in Monument Box and accepted as a careful and faithful perpetuation of the position of the original corner.

Liber 1, Page 491 07-06-72
WNW 47.09 24" Oak
WSW 39.97 Twin Catalpa
NE 4.35 17" Oak



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Cast Iron Monument

O.C. Remon Tag & Nail in N side Twin 15" Catalpa	AZ 248°	39.60
O.C. Remon Tag & Nail in S side 30" Oak	AZ 286°	47.60
O.C. Remon Tag & Nail in NW side 18" Oak	AZ 39°	4.70
SE corner of Block Foundation House #230 Fruitport Road	AZ 310°	67.40

Signed by Thomas E. Joiner Date 11-16-95

Surveyor's Michigan License No. 18435