## RECORDED OTTAWA COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 15 AM11: 46

For corners in	i iiiig iicquii	Cilicili Ol Act 1-	t, whom I im. (310	Physilia Kielman
Ottawa	Located In:	Corner Code	e -++	REGISTER OF DEEDS
(County)		Comer cou	<del></del>	SURVEY &
	ON 1.677	7 2 01 0		
<ol> <li>Public Land Survey</li> </ol>	T 8N R 16W	L-3, Sł Co		REMONUMENTATION
	T R	Section 1		•
	T R	Spring Lal	ke Twp.	JEC 6 5 2000
	T R	·		JE0 0 0 2000
2. Property Controlling	S T R			
in Section	S T R			CECTION
3. Miscellaneous	S T R		Regi	ister of Deeds Stamp & File Number
Property in Sec.	S T R	4		
	Recorded Plat			ABCDEFGHIJKŁM
5. Private Claims			<u> </u>	
				3 1 1 1 1 1 1 1 1 1 1
_				
· TUOMAS Folow	////un a field survey on	11-21-	94	*   -
do beroby certify that under re	r∡∕an a neig survey onequirements of P.A. 74, Michigan P.A	of 1970, the corner	_ , 19 ,	5
	in conformance with regulations a			6 18 17 16 15 14 13
	ructions of the United States Depa			7
	faCourt of Law and/or that the corn	•		8 19 20 21 22 23 24
	ith the rules of the Michigan Board	•	-	9
expressed below:	re-established, monumented, re-	monumented, reco	vered, tound as	10 30 38 37 36 36
•	Namana all la Aba sauce Associa			11
	corners, all in the same town a	no range, may be	recorded	
on this certificate	•			12 31 32 33 34 35 36
A Description of original	monument and accessories an	d/or subsequent i	restoration:	13
03-28-1837		Pg. 7, 11-3		Liber 6, Pg. 237, 09-15-92
Post Set by John M	ullet, D.S. Found St			Found Cast Iron Monument
N 09°E 32 16" W.	Oak East 29.	69 Power Po.		ENE 23.95 & Top of Hydrant
S 30°W 11 18" W.	Oak SE 83. WNW 42.	26 6" Catal <sub>1</sub> 51 9" Popla	pa r	SW 73.45 ½" Iron w/Cap
Liber 1, Pg. 81, 0		84 13" Pop la	ar	West 33.00 ½" Iron w/Cap
Found Iron Bar	MMW /4.	46 6" Metal	Guard Post (fa	
East 29.69 Power		Pg. 52, 05- : Iron Monume	17-83 n*	Post filled w/con
SW 107.41 30" 0 SE 82.72 6" Ca		64 Power Po.	nc 1e	ENE 29.64 P.P.
NW 49.24 10" T	win Oak NW 81.	76 Triple 10 84 12" Popl.	6" Maple	West 47.84 12" Poplar
MU 40 47 2011 0	ak West 47.	84 12" Popla	ar	
B. Description of corner of	evidence found and/or method	applied in restorin	g or reestablishing o	corner:
TOURG DIGHTER OIL T			and accepted as	s a careful and faithful
perpetuation of th	e position of the orig	inal corner.		
	0.04.33		F0 05 17 00	
Liber 1, Pg. 81, 0			. 52, 05-17-83	
SE 82.72 6" Cat		ENE 29.64		•
East 29.69 Power	Pole	West 47.84	iz ropiar	
Liber 4, Pg. 7, 11	_20_70	Idhar 6 Da	. 237, 09-15-92	)
East 29.69 Power			E Top of Hydra	
			½" Iron w/Cap	431 <b>C</b>
SE 83.26 6" Cat WNW 42.51 9" Pop				teel Post filled with conc.
NINU 74 46 6" Met	al Guard Post (face)		-	COCT TOUT TITLOG WITH COME.
WNW 47.84 13" Po		West 47.84		
WWW 47.04 13 10	PIGE	11000	of	
C. Description of monume	ent for corner and accessories	established to per	petuate locating the	position of the corner
	on Monument in Monumer			position of the corner of MiCHIGAN
€ Top Operating Nu	t on Hydrant		Az. 78°	
O.C. Remon. Tag &	Nail in NW side 12" Ca		Az. 140°	83.07 / <b>JOINER</b>
O.C. Remon. Tag &	Nail in N side 13" Oal	ζ	Az. 270°	41.30 LAND SURVEYOR
O.C. Remon. Tag &	Nail in side Twin 18"	Oak	Az. 328°	81.64 \\ 18435
		045 OT	TAWA COUNTY	Coulered Land Surrent
PEER APPROVED 12/13/99				
		<b> • •</b>	, ,	
Signed by	as C. Larnis.		Date	12-94
Signed by	100125	·-···		!
Surveyor's Michigan Licens	Se No	· · · · · · · · · · · · · · · · · · ·	FORM APPROVE	EO BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971