

SURVEY & REMONUMENTATION

APR 24 1995

COMMISSION

For corners in
Ottawa
(County)

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AM 11:47

Phyllis Kallman
REGISTER OF DEEDS
OTTAWA COUNTY, MI

	Located In:	Corner Code #
1. Public Land Survey	T <u>9N</u> R <u>13W</u>	I-3, NE Cor.
	T _____ R _____	Sec. <u>10</u>
	T _____ R _____	Chester Twp.
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

I, Randal D. Feenstra, in a field survey on December 8, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	16	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. by Rasselas Whitcomb	L-5, P-46, 1983
Sept. 17, 1838	C.I.M.
POST	26" Maple NE 42.18'
45" Lymm S28 E 28 Links	Cor. Brick Church NW 85.14'
24" Sugar N54 W 41 Links	16" Chestnut NE 66.13'
	St. Sign SE 52.70

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found: C.I.M. in box (No Cover) and is accepted as a careful and faithful perpetuation of the position of the original corner.

Nail in S side 24" Chestnut NE 66.03'
Nail in W side 40" Maple NE 42.17'
SE Cor. Brick Church NW 85.19'

P.A. 345 OTTAWA COUNTY
PEER APPROVED 12/12/94
Wendy D. Medwell

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-3 C.I.M. in box
O.C. Remon. Nail & Tag in W side 40" Maple N45 E 42.14'
O.C. Remon Nail & Tag in S side 24" Chestnut N60 E 66.05'
SE Cor. Brick Church N40 W 85.19'
SW Cor Block Wall @ entr. of church N55 W 80.04'
1' W and 0.5' S of CL "x" Truman Street and 16th Avenue



Signed by Randal D. Feenstra

Date December 8, 1994

Surveyor's Michigan License No 37275