RECORDED

OTTAWA COUNTY REMONUMENTATION

99 DEC -2 PH 1:12

LAND CORNER RECORDATION CERTIFICATE

	LAND	CORNE	R RECORDATIO	N CERTIFICA	TE	0	20.	18-		
For corners in	Filin	g Requi	rement of Act 74,	Mich. P.A. 197	טי	Panj	nas ne	<i>(m)</i> ene		
ΟΤΤΛΙΛΙΔ						REGISTI OTTSWA	R OF OE	. M		
(County)	ated in:	Cor	ner Code#	1						
•	T9N R_	13W	K-2 W 1/4 Corne	r		2				
1. Public Land Survey			Section 1. Chest		sed.					
	TR_		Twp	7						
C. Daniel and Cambralling.	TR_ TR_									
2. Property Controlling S_ in Section S_	'`~									
3. Miscellaneous S_	TR_			İ						
Property in Sec. S_	TR_				Reg	gister of D	eeds Sta	mp & Fil	e Num	<u>iber</u>
4. Lot No, Recorded P 5. Private Claims	iat			 -	1 A B	Ср	E F G	H I	JΚ	LN
5. Private Claims					2 -	5	│	_3	-2 -	ļ
•					3		 		 - -	- -
Randal J. Vugteveen in a requirements of P.A. 74, Michigan P.A.	field survey on	Novembe	or 6 , 1999 do hereby	state that under	4		 -	10	-11	12
requirements of P.A. 74, Michigan P.A. conformance with regulations and rules the	of 1970, the corn	er points m	entioned in lines 1 and	2 above were in	5				╌┼╌	
United Cintes Department of the Interior	Rureau of Land M	<i>l</i> lanademen	t or by a decree of a Cou	ift of Law and /or	6 -1	0-17-	16-	15-	-14	-13
that the corner points mentioned in lines Board of Land Surveyors or by a Dec	3. 4 and 5 above	were in col	nformance with the fule:	OT THE MICHIGAN	7		┝╌┼╌┤	++	+-+	
recovered, found as expressed below:					81	92'0	21	-22-	-23	24 !
NOTE: Not more than 2 corners, all	in the same tow	vn and ran	ge, may be recorded		9	- - -			++	_
on this certificate.			·		10 -3	0	28	27	-26 -	25
				\$	11			34	7.	_36_
					12 3	132	-33-		ĭI	
A. Description of original monumer	nt and accessor	ries and/o	r subsequent restorat	ion:	13					
K-2 Peer Approved Corner Liber 3, Page										
(Feenstra September 16, 1996)						37 A 7 C 4 P	* *	j w		
K-2 Cast Iron Monument in Gravel Road				Charles Ch		TAWA .	.)	/a.a	,	
Nail & Remon Tag in S side 8″ Beech Az 43.35'	2313-				1 1 1 1 2 1		\ <i>\\\</i>			,
Nail & Remon Tag in E side 18" Ash Az	346* 86.20'						11)	7/		
Nail & Remon Tag in top fence post Az 2	23° 76.42'					$, \mathcal{I}$		6		
Nail & Remon Tag in N side 8" Cherry A CL 8th Ave. (gravel) N& S 3.0' W	275* 27.38									
B. Description of corner evidence	found and/or m	nethod ap	plied in restoring or re	establishing cor	ner:					
K-2 Found Cast Iron Monument			,				•			
K-2 Found Cast non Monoment									O.	
Found Nail & Remon Tag S side 8" Bee	ch N45°W Ac	cepted Ca	st Iron Monument as a of the position of the	careful and		" X 24" Lon Cap at inte				Junty
43,35' Found Nail & Remon Tag E side 18" Asl			ess outside of constru		· Cinon	Oap at mic				
86,20°										
Found Nail & Remon Tag Top fence pos	at N25°E									
76.42' Found Nail & Remon Tag N side 8" Che	my N75°E									
27.38	1				ł					
C. Description of monument for co	mer and access	sories est	ablished to perpetuat	e locating the po	sition of	the come	r:			
K-2 3/4" X 24" Long Solid Bar with Rem	on Cap									
						,				-
Set Nail & Remon Tag in S side 10" Elm	n N84°E 50.16'						7 Y.S	NDALJ. STEVESN	3	7
Set Nail & Remon Tag in NE side 4" Eln Set Nail & Remon Tag in Top of N end	л N55°W 81.53° 12° CPP Culvert	N27°W 56	.01'				3	NO.	5 P	Receirt
Set Nail & Remon Tag in Top of Send	12" CPP Culvert	S31°W 45	5.89'	ī		, Şç		284 27		*
Iron Witness Point N46°E 72.71°	_	/		•		عمر		and the said	1. 1. 2	#64945
Iron Witness Point S51°E 61.36'	11/1	/			,		, , , , , , , , , , , , , , , , , , ,	العاديان المالية	.*-	*****
	1 HA			1		سرا	100	9		
Signed by	. Ih	>		Date	VOV.	12,	177	<u></u>		
Surveyor's Michigan License No	2812	9								