DEC 1. 6 1996

Surveyor's Michigan License No.\_

COMMISSION

JUDITH D. ROEHN 06/10/96 Ontonason County 15:38 LC 4/ 69 JEM Fee: 9.00 Page 1 of 1

For corners in		ND CORNER RECORI		Ē	rage 1 OT	1
ONTONAGON		O				
(County)	Located In:	Corner Code #		_		
1. Public Land Surve	T T	R 39W G-7 R	_	<b>V</b>		
Property Controllin In Section Miscellaneous Property in Sec.	g	RRRRR		Register of Deed	ls Stamp & File N	umber
4. Lot No, F 5. Private Claims	Recorded Plat		1	A B C D E	FGHIJ	K L M
Section Corner	r common to Sect	ions 15, 16, 21 &		- 6- <del> 5- -</del>	4-1-3-1-2-	<del></del>
requirements of P.A. 74, No conformance with regulation United States Department that the corner points mer Board of Land Surveyors recovered, found as express	Alchigan P.A. of 1970, the one and rules therefore as required the interior, Bureau of Landoned in lines 3, 4 and 5 about a Decree of a Coused below:	on <u>May 06</u> , 19 <u>96</u> do corner points mentioned in lines ulred in the current manual of s d Management or by a decree of overwere in conformance with that of Law, established, re-established	1 and 2 above were in urvey instructions of the of a Court of Law and /or he rules of the Michigan ablished, monumented,	-18 -17	9 10 11 14 14 21 22 23 1	1324
on this certificat	te.	town and range, may be reco	10 12 12	3029	28 27 26 33 34 35	36
_	er established by cember 21, 1851.	y Artemas Curtis, Set Wood Post.	U.S. Deputy			
ORIGINAL BEARI	ING TREES:		P	EER GROUP A	PPROVED	•
White Pine 14 White Pine 16		2 links 21 links		OUNTY MITTO	pleka-po- 6-06-96	₽
B. Description of corn	er evidence found and/o	r method applied in restoring	g or reestablishing corner:		- 76	
corner position monument box in has been in experience of the surveyors for	on I found a $\frac{1}{2}$ "; in the centerline distance for 35 y	d, except stream of Iron Pin with a ca e of U.S. Highway years. It has been n the area. I acc	p marked 16936 in 45. This corner on used by several	n a position l	EARL W.	CANALA TA
Research on fi	ile with the Onto	onagon County Remo	onumentation Repre	esentative. 5	PROFESSIONA SURVEYOR NO.	LEYOR X
C. Description of monu	ument for corner and acc	essories established to pen	petuate locating the positio	n of the corner:		ed its
centerline of $2\frac{1}{2}$ " aluminum p R.M., T48N R39	U.S. Highway 45. Sipe with a 3½" o	the ½" Iron Pin is: I established to real, S22, 1996, P.S.	wo reference monu d: County Remonu	ments which mentation,	POFESSIONA are	issun.
		55.13' P. Pole 63.33' P. Pole	N27°-01'-19"v S31°-18'-41"E		;	