REMONUMENTATION

DEC 1 6 1996 .

JUDITH D. ROEHM Ontonason County 4/ 93 JEM LC

07/11/96 03:45

Fee:

Page 1 of 1

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

|  | *   | • • • • •   |   |   |  |        |
|--|---|---|---|---|--|--------|
| For corners in   |   |   |   | ·   |  | •      |
| ONTONAGON (County)   | Located In:   | Corner Code #   |   | N.  |  |        |
| 2. Property Controlling in Section 3. Miscellaneous Property in Sec.  4. Lot No, Reco. 5. Private Claims  1 Corner common to Learl W. Applekamp requirements of P.A. 74, Michig conformance with regulations ar United States Department of the that the corner points mentione Board of Land Surveyors or recovered, found as expressed in the corner points mentione and the corner points mentioned and the corne | TR TR STR STR STR STF STF STF STF STF STF STR | 34, T47N &T48N, R40.  May 22_, 1996_ do hereby to mer points mentioned in lines 1 and 2 lifted in the current manual of survey inside the | structions of the<br>rt of Law and /or<br>of the Michigan | Register of Deeds  A B C D E F  2 6 5 4  3 4 7 8 5  6 18 17 17 1  7 8 19 20 6 | S Stamp & File Number  F G II J K L  4 - 3 - 2 - 1  9 - 10 - 11 - 12  16 - 15 - 14 - 13  21 - 22 - 23 - 24  28 - 27 - 26 - 2 |        |
| on this certificate.   | ·   |   |   | 11 12 31 32   | 33 34 35 3   | <br>36 |
| A Description of original n  | nonument and access   | sories and/or subsequent restorati  | ion:  | 131   |  |        |

Original corner established by John Burt, U.S. Deputy Surveyor, July 13, 1850. Set Maple Post.

ORIGINAL BEARING TREES:

11 links Cedar 14" N76°E N40°W. Cedar 18" · 41 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner was re-established by single proportionate measurement between opposite section corners East & West and using the existing old fence line to set the latitude.

PEER GROUP APPROVED DEPARSENTATIVE COUNTY 07-08-96

Research on file with the Ontonagon County Remonumentation Representative.

Steel Sisn Post North 1.63'

APPLEKAMP

PROFESSIONAL

| C. Descriptio | n of monume | nt for corner and a         | ocessories established i                            | to perpetuate          | locating the position          | of the corner. |
|---------------|-------------|-----------------------------|---|------------------------|--------------------------------|----------------|
| at the c      | orner pos   | sition I set<br>County Remo | a 2½"X30" alum<br>numentation, 4<br>nree bearing tr | inum pipe<br>, T47N, T | with a 3½" c<br>148N, R40W, 19 | ap 96,         |
| 6" Oak        | N70°W       | 54.88'                      | 4" Spruce   |                        | 36.92'                         |                |

SURVEYOR NO.

| 90 41                           | 0 00   |
|---------------------------------|--|
| Signed by Lack W                | applekaup  |
| Surveyor's Michigan License No. | <u> 17610                                     </u> |

53.13'

June 20, 1996 Date

4

12" Oak

N13°E