## SUHVEY & REMONUMENTATION

APR 2 9 1996

JUDITH D. ROEHM Ontonagon County 09/28/95

1 of

## LC

3/331 JEM Fag**e** 

CO	2 2 5	A) C	011	Shi
	IMI	VIII.	. TIL	111

LAND CORNER RECORDATION CERTIFICATE

Fo	or corners in	Filing Requir	rement of Act 74, Mich. P.A	. 1970							
_	Ontonagon	Located In:	Corner Code ##								
1.	Public Land Survey	T _48N_ R _42W_ T R T R T R	C-6								
2.	Property Controlling	S T R									
	in Section	S T A									
3.	Miscellaneous	S T R	<u> </u>	Registe	r of D	aade S	tamn.	& Fila	Nue	shar	
	Property in Sec.	S T R					tamp				
4. 5.	Lot No, Re	ecorded Plat			В	СБ	E F	G Н	i J	ĸ	L M
		mon to Sections 18 and 17, T48		2	6	5	4-	- 3-	<del> </del>		-
	-			3 4		8		10_	<del>  </del>	1	-12-
١, _			eptember 14 19 95					<u> </u>	$\downarrow \downarrow$		
	do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					17	16	15_	14	<u>.                                    </u>	) -13
			rd rules therefore as required in t rtment of the Interior, Bureau of La							$oldsymbol{\perp}$	1_
		·	er points mentioned in lines 3, 4 and			20	—21 <i>-</i>				Ţ
	above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						—21~~~ 		1-23		-24
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:									17	十	_
				10	—30-—i	2 <sup>9</sup>	—-28	<u> </u>	1-26	<u> </u>	-25
NC		orners, all in the same town a	nd range, may be recorded	11	_	$\vdash$	<del></del>	$\vdash$	╂╼╀	_	+-
	on this certificate.			12	/-	ا ماما	ساسا	مات ا	ما ا	. 1	الدلا

- Description of original monument and accessories and/or subsequent restoration:
  - On August 10, 1848, Austin Burt set an ironwood post from which a 12" sugar bears N20°W, 27 links and a 16" sugar N74°E - 8 links.
  - Survey dated May 13, 1978, by Earl Applekamp, RLS 17610, found a 2" diameter iron pipe at 1/4 corner location which is shown on his Plat of Survey.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner: В.

Found 2" iron pipe as noted above and accepted corner as being in correct position as it has been used in several surveys of record.

Record research on file with Register of Deeds.

EER GROUP APPROVED

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 2 1/2" diameter x 30" long aluminum pipe with a 3 1/4" diameter aluminum cap stamped: County Remonumentation; T48N; R42W; 1/4; S-18; S-17; 1995; RLS 28410, from which the following bearing trees and/or reference objects:

9" sugar - N53°E - 19.38 feet 11" sugar - S53°E - 20.00 feet 10" sugar - N42°W - 22.84 feet

6 foot steel rai with sign - S76°W - 1.41 feet

Signed by 28410 Surveyor's Michigan License No.

No. 28410

OFMICA

JOHN R. GARSKE

LAND SURVEYOR

FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED JAN., 1983