## SURVEY & REMONUMENTATION

APR 2 5 1995

Surveyor's Michigen License No. 28410

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For come	_			•
	Ontonagon	Located In:	Corner Code ##	· · · · · · · · · · · · · · · · · · ·
	(County)		Ourier Odds	Recorded Occambe 71994
				41/5 0'000K 1 Main
1. Public	c Land Survey	т <u>48N</u> R <u>42W</u>	F-11	nogo ~.)
	·	T R		liber 3 10 alex depor
		T R		Register of Deeds
		· n		A Mediator of peors
		T R		
2. Prope	erty Controlling	S T R		$\smile$
in Se	ction	S T R		
3. Misce	ellaneous	S		Deciator of Deads Chaus 9 File North and
Prope	erty in Sec.	S T R		Register of Deeds Stamp & File Number
.,561	,	,,		
4 1-441	. D.	annudad Diak		
				A B C D E F G H I J K L
One-	-quarter corne	er common to Sections	28 and 33, T48N, R42W	· 2 - 6 5 4 3 2 1 -
			•	3]
Johr	n R. Garske	in a field survey onOct	toher 26 10 04	
			of 1970, the corner points mentione	<u></u>
			nd rules therefore as required in the	
			tment of the Interior, Bureau of Lar	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				
expressed		established, inbhumented, re-	monumentea, recoverea, touna a	
•				50 20 20 20 20 20
10TE: N	lot more than 4 co	rners, all in the same town a	nd range, may be recorded	11 <del></del>
C	on this certificate.			12 31 32 33 34 35 36
				13
A. Desc	ription of original m	nonument and accessories an	d/or subsequent restoration:	
3. Desc	On July 25, 19 with a squared Pierce - 6/4/36 feet, 3 tags in a ription of corner evaluation of corner evaluation which his quarter corner	wood post and a 12" blaze H.W. Cole, L.A. Pointe a 12" cedar with blaze, beautidence found and/or method idence could be found due as been used in various sur	r set by Robert Mick, RLS ed cedar tagged with the foll - 8/27/41; Turney - 3/26/52 ars - N10°W, 11.36 feet.	ishing corner:  ted the found rebar as noted er companies as the one-
	Collier record	research on the.		
				PEER APPROVED
				0- 11 11
				Lail W lipplekaup Co Rep. 30-94
				P. B.
				co rep.
				11-30-74
				·
). Desci	ription of monumer	nt for corner and accessories	established to perpetuate locat	ing the position of the corner:
	Lundated the	orner position to state and	county enecifications by	placing rebar with a 2 1/2" x
	30" aluminum 33; T48N, R42 object: 12" ce	pipe with a 3 1/4" aluminu 2W; 1994; RLS 28410. I c	om cap stamped: County Restablished the following beat 8" hemlock - N52°E, 18.94	monumentation; 1/4; S-28; S- aring trees and reference feet; 6" maple - S87°E, 8.74
				JOHN R. **  GARSKE **  LAND SURVEYOR

FED No. V-11 237

D PY-MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28, 1971 REVISED MAY 14, 1975 AEVISED JAM., 1983