## TEMONUMENTATION

APR 2 9 1996

Surveyor's Michigan License No.

JUDITH D. ROEHM Ontonagon County

12/18/95

4/ 11 JEM F

Page

15:02 9.00

1 of 1

COMMUSSION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 19	070
For corners in	
ONTONAGON Located In: Corner Code #	
1. Public Land Survey	
T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	ABCDEFGHIJKL
	2 6 5 4 3 - 2 1
Section Corner common to Sections 1, 2, 11, & 12, T48N R43W.	3
I, Earl W. Applekamp, in a field survey on July 28, 19,95 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	4
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25
•	11
	12 31 32 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: Original corner established by Austin Burt, U.S. Deputy Survey August 15, 1848. Set Sugar Post. ORIGINAL BEARING TREES:	yor on
Lynn 14" S50°W 38 links (25.08 feet) - Hemlock 14" N65°E	3 linke (1 98
Corner position monumented by RLS 21583 with a $1\frac{1}{4}$ " diameter in August 1981. Recorded in Liber 2, page 8. Corner was remonumed 21564 in July 1991, with a $2\frac{1}{2}$ "x30" aluminum pipe with a $3\frac{1}{4}$ " can Liber 3 page 176, April 22, 1993. B. Description of corner evidence found and/or method applied in restoring or reestablishing contact.	ron pin, mented by RLS ap. Recorded
On July 28, 1995 I needed this corner for a survey in the area monument had been broken off at the ground level. I re-estable the corner, using the ties shown on the corner certificate and a monument as shown in "C" below.	Lished
Research on file.	EARL W.
C. Description of monument for corner and accessories established to perpetuate locating the po	A APPLEKAMP A PROFESSIONAL Sition of the corner: SURVEYOR
At the corner position I set a $2\frac{1}{2}$ "x30" long aluminum pipe with stamped to read: COUNTY REMONUMENTATION, S1, S11, S12, T48N R4P.S. 17610. I re-painted bearing trees shown on 1993 corner cestablished an additional bearing tree and set a new sign post	ertificate, OFESSIONAL TRIP
8" Red Maple N08°E 23.37 feet - 4" Maple N47°W 57.57" Red Maple N49°E 30.24 feet - Steel Sign Post, East 8" Sugar Maple N72°E 23.24 feet PEER GROUP APPRO	64 feet (new) 2.94 feet (new)
COUNTY REPRESENTATI	IVE

Date December 06, 1995